SURVEY & REMONUMENTATION

MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'98 MAR 6 PM 12 36

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

A. carro Banes

NORMAN L. OCHS LAND SURVEYOR

22439

For corners in Newaygo (County)	Located in:	Corner Code#	Q.	ide M. Olso
Public Land Survey	T <u>14N</u> R <u>13W</u> T R T R	<u>E-9</u>	vol. 2	10 8
Property Controlling in Section Miscellaneous Property in Sec.	TR STR STR STR		Register of Deeds Stan	np & File Number
4. Lot No, Record 5. Private Claims, Record 5. Private Claims, Record 6. Private Claims	, in a field survey on Novemblairements of P. A. 74, Michigan P. above were in conformance with ent manual of survey instructions au of Land Management or by a ints mentioned in lines 3, 4 are the Michigan Board of Land lished, re-established, monumer elow:	Der 1 , 19 97 , A. of 1970, the corner regulations and rules of the United States and eccure of a Court of the Surveyors or by a nited, re-monumented,	A B C D E F 1	G H I J K L M 3 - 2 - 1 - 10 - 11 - 12 - 15 - 14 - 13 - 22 - 23 - 24 -
Southwest Corner, Section 2	21, Lincoln Township, Neway	go County, Michigan.	$\frac{12}{13}$ $\frac{31}{13}$ $\frac{32}{13}$ $\frac{33}{13}$	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1856 8" Beech N65°W 15 Links (9.9')#1 7" Beech S65°E 13 Links (8.58')#2

Delos G. Anderson (County Surveyor)
Book A Pages 179 and 180 October 12, 1895
Original Corner

Ralph A. Smith, R.L.S. #3421 Witness Book Number 1 Page 36 1" Gas Pipe October 25, 1956 Forestry Post N10°W 31.3' #3 10" Beech S50°E 10.3' #4

Newaygo Engineering and Survey Company LCRC #591 December 22, 1978 Found a 1" Pipe. Centerline of trail road going East is 18 feet South of corner. 16" Beech S48°E 10.66' #4 10" Red Oak N10°E 2.82' #5 18" Forked Beech N65°E 20.35' #6

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1" X 22½" Pipe and three stones (5" in diameter) piled around it. In the centerline of old North and South road. The centerline of the old trail road going East and West is 17 feet South. The condition of the recorded witnesses are: #1 and #2 gone, #3 leaning, #4 good condition, #5 stump, #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 1" Pipe and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" with stones piled around, as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Forestry Post (leaning) N15°W 31.3' to center of post. #3
30" Beech S50°E 10.63' Found spike in North side of tree. #4
Oak Stump N07°E 2.82' Found spike in Southeast side of tree. #5
30" Forked Beech N60°E 20.35' Set spike and brass washer in Southeast side of tree. #6
10" White Oak S69°W 63.50' Set spike and brass washer in North side of tree.
8" Maple N56°W 49.91' Set spike and brass washer in North side of tree.
Signed by Appendix A Company Date November 10, 1997
Signed by Date November 10, 1997

Surveyor's Michigan License No. <u>22439</u> Form approved by Michigan State Board of Land Surveyors, Jan 26	11.00
	•
Revised May 14 Approved by Peer Review Group on November 11, 1997 Revised Jan.	

Approved by Peer Review Group on <u>November 11, 1997</u>
Norman L. Ochs, County Representative.

ntative.