

MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

TO DEPARTMENT

to the South One Quarter Corner of Section 10

LAND CORNER RECORDATION CERTIFICATE

207 FER 12 PM 4 4

COMMISSION	FILING REQUIRE	MENT of Act 74, Mich. P.A	. 1970	GITED.	1.6 111 1
For corners in Newaygo (County)	Located in:	Corner Code#		Sunda	v M. Bro
1. Public Land Survey	T <u>14N</u> R <u>13W</u> T R T R T R	G-5	vol. $oldsymbol{2}$	PAGE	13
Property Controlling in Section Miscellaneous	STR STR				
Property in Sec.	SIR	Regis	ter of Deeds Sta		
do hereby certify that under require points mentioned in lines 1 and 2 at therefore as required in the currer Department of the Interior, Bureau Law and/or that the corner point conformance with the rules of Decree of a Court of Law, establis recovered, found as expressed belonger. Note: Not more than 4 cornered on this countly well as the country of the country o	n a field survey on November 21 ements of P. A. 74, Michigan P.A. above were in conformance with regit manual of survey instructions of of Land Management or by a district of the Michigan Board of Land Sched, re-established, monumented ow: orners, all in the same to ertificate.	of 1970, the corner guiations and rules the United States ecree of a Court of 5 above were in urveyors or by a d, re-monumented,	2		
		,	CODOLQOLIV	I KESTOKA	iion.
G.L.O. Milton Nye Resurvey 1856 8" Maple N42°E 20 Links (13.2')#1 18" White Oak S67½°W 17 Links (11.22')#2		Newaygo Engineering and Survey Company Found Fence Post and old fences on ground running North and West April 20, 1979 Dug around tree - Found nothing			
William M. Jacques (County S Book 8 Page's 61 and 62 Jan Measured 40.06 Chains (2643 Quarter Corner to the Southea measured 39 Chains (2574') fi	uary 31, 1906 i.96') from the South One ist Corner of Section 9 and	Patrick R. Leemon R.L.S. # 1983 Section Break, Section Measured 2586.40 feet from Quarter of Section 15 and n Corner to the West One Qu	on 15 on the Northwest C neasured 2878.14	feet from the N	Northwest

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found nothing. Set Harrison monument at intersection of fence line going North and fence line going West and measured 2688.73 feet from the Southwest Corner to the West One Quarter Corner of Section 10 and measured 2609.30 feet from the Southwest Corner to the South One Quarter Corner of Section 10 and measured 2868.94 feet from the Southwest Corner of Section 10 to the East One Quarter Corner of Section 16 and the condition of the recorded witnesses are: #1 and #2 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

12" White Oak N45°E 12.13' Set spike and tag in Northwest side of 8" White Oak S30°E 31.16' Set spike and tag in East side of tree. 12"-16"-15" Triple Maple S37°W 19.01' Set spike and tag in East side.	de of tree.			
24" Black Oak N36°W 35.73' Set spike and tag in Southwest side of tree.				
Signed by Mormon L. Ochs Norman L. Ochs	DateNovember 30, 1996			
Norman L. Ochs				
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971			
	Revised May 14, 1975			

Approved by Peer Review Group On <u>December 11, 1996</u>

Norman L. Ochs, County Representative.

Revised Jan., 1983

