

MAY 2'S 1997

COMMISSION

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE '97 FEB 12 PM 4 45 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	Corner Code #	Lin	sa M. L	Prouve
1. Public Land Survey	T <u>14N</u> R <u>13W</u> T R T R	G-6	VOL. 2	PAGE	14
Property Controlling in Section Miscellaneous	TR STR STR		YUL. 🕰	FAUE	17
Property in Sec.	STR		Register of Deeds S	tamp & File N	Vumber
do hereby certify that under reconsts mentioned in lines 1 and therefore as required in the curberartment of the Interior, Burnaw and/or that the corner proportions with the rules of the second or that the corner proportions.	, in a field survey on November 20 puirements of P. A. 74, Michigan P.A. of 19 2 above were in conformance with regulation from the manual of survey instructions of the eau of Land Management or by a decree oints mentioned in lines 3, 4 and 5 about the Michigan Board of Land Survey blished, re-established, monumented, re-	070, the corner cons and rules United States of a Court of cover were in vors or by a	2		
Note: Not more than 4 recorded on this	corners, all in the same town a certificate.	and range, may be	e 12 31 32-31-13	-0334-	

East One Quarter Comer, Section 16, Lincoln Township, Newaygo County, Michigan

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1856 5" Beech N70°W 28 Links (18.48')#1 4" Beech S61°E 20 Links (13.20')#2

Measured 85.66 Chains (5653.56') from the Northeast Corner to the Southeast Corner of Section 16 and measured 42.83 Chains (2826.78') from the Northeast Corner to the East One Quarter Corner and measured 42.83 Chains (2826.78') from the East One Quarter Corner to the Southeast Corner of Section 16.

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found nothing here. Found stumps 500 feet ± North, could be line trees. Set 4" X 20" Harrison monument on intersection of fence line and on line between Northeast and Southeast corners of Section 16. Corner is on slope of hill 75 feet ± East of crest on hill and on woods line going West and scattered remains of fence line going West (very old - had to dig to find) and measured 5699.09 feet from the Northeast Corner to the Southeast Corner of Section 16 and measured 2868.94 feet from the Northeast Corner to the East One Quarter Corner and measured 2830.15 feet from the East One Quarter Corner to the Southeast Corner of Section 16 and the condition of the recorded witnesses are: #1 and #2 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

15" White Oak N20°W 15.66' Set spike in East side of tree. 18" White Oak N42°E 10.43' Set spike in Southeast side of tree. 6" Maple S50°E 17.01' Set spike in Southwest side of tree. 15" Red Oak S65°W 16.17' Set spike in Southeast side of tree. Signed by	Date <u>Nove</u> mber 30, 1996
Norman L. Ochs	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
	Revised May 14, 1975
Approved by Peer Review Group On	Revised Jan., 1983
Norman L. Ochs, County Representative.	

NORMAN
L. OCHS
LAND
SURVEYOR
22439