

MAR 0 2 1999

1998 Newaygo County Remonumentation Project REGISTER OF DEEDS

NEWAYGO COUNTY

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '99 FEB 17 PM 3 41

For corners in			001607	
For corners in Newaygo	Located in:	Corner Code #	. 0	Δ
(County)	*		Sinda	M. Brown
1. Public Land Survey	T <u>14N</u> R <u>13W</u>	K-3		
•	TR		VOL. $oldsymbol{2}$	255
	TR TR		10L. 14	200
2. Property Controlling	STR			
in Section 3. Miscellaneous	STR STR			
Property in Sec.	STR	R	egister of Deeds Stam	o & File Number
4 Let No.	ded Diet			
5. Private Claims	ded Plat		1 T T T T T T	HIJKLM
			2 6 + 5 + 4 +	-3 + 2 + 1 -
I, Norman L. Ochs	, in a field survey on <u>November 3</u>	0.19.98.	3 - 1 - 1 - 1 - 1	-1-1-1-1-1
do hereby certify that under require	rements of P. A. 74, Michigan P.A. of above were in conformance with regula	1970, the corner		10 + 11 + 12 +
therefore as required in the curren	nt manual of survey instructions of the	United States	5 19 17 17	17 11 10
Department of the Interior, Bureau Law and/or that the corner point	u of Land Management or by a decreate mentioned in lines 3, 4 and 5 a	ee of a Court of	6 18 + 17 + 16 +	- 15 + 14 + 13 -
conformance with the rules of	the Michigan Board of Land Surv	eyors or by a		-22 + 23 + 24 -
recovered, found as expressed be	shed, re-established, monumented, r low:	re-monumented,	9 19 20 21	22 23 24
,			10 - 30 + 29 + 28 +	-27 + 26 + 25
recorded on this ce	orners, all in the same town	and range, may be	11	
			12 - 31 + 32 + 33 +	-34 + 35 + 36 -
Southeast Corner, Section 2,	Lincoln Township, Newaygo Cou	nty, Michigan.	13	
A. DESCRIPTION OF OR	IGINAL MONUMENT AND A	CCESSORIES AND/O	R SUBSEQUENT RES	STORATION:
		,		
G.L.O. Milton Nye 1856 Resurvey Robert A. Griffin R.L.S. #13 6" White Oak N03°E 23 Links (15.18')#1 LCRC #576 1983 Four			.S. #13584 Found Iron object (di	id t \ t d
6" White Oak S36°W 221/2			ar raised with a ½" X 20	
	, ,		Set a 5" X 60" Concrete	
Ralph A. Smith R.L.S. #342	21 Oak Stake and ½" Gas Pipe	cap. 8" Black Oak N13°W	174 221 #F	
15" Black Oak S60°E 54' #		5" White Pine N35°E		
14" Black Oak S03°E 46.2	#4	12" White Oak N43°	E 84.42' #7	
		Fiberglass Post Nort	h 38.35' #8	
B. DESCRIPTION OF CO	RNER EVIDENCE FOUND AI	ND/OR METHOD API	PLIED IN RESTORING	OR
REESTABLISHING CORN				
Found 5" X 5" concrete mo	onument. The centerline of the	e Fast and West hitum	singus road is 4 feet + 9	South and the
centerline of a two-track go	oing South is 6 feet ± West. TI	here is no apparent oc	cupation going North.	The condition of the
recorded witnesses are: #1	thru #3 gone, #4 thru #8 goo	d condition.		
C. DESCRIPTION OF MO	NUMENT FOR CORNER AN	D ACCESSORIES ES	TABLISHED TO PERI	PETUATE LOCATING
THE POSITION OF THE C	ORNER:			
Accepted 5" Y 60" Concret	o Monument de a culestantial :	manulcar for the anathem		
faithful reestablishment of	e Monument as a substantial : the original corner.	marker for the section	corner and is accepted	as a careful and
	•			
20" Black Oak (blazed) Soi 14" Black Oak (blazed) N1	uth 46.34' Set spike with tag# 1°W 71.05' Found dock spike	22439 in East side of t	tree. #4 :=	
6" Red Pine (blazed) N38°l	E 53.23' Found dock spike in \	Nesterly side of tree. #	±6	
16" White Oak (blazed) N4	5°E 84.45' Found dock spike i	in Northwesterly side of	of tree. #7	
Carsonite Post North 38.4'	± to center #8			
Signed by 10ma	n T. Ocho	DateDec	ember 4, 1998	
Norman L. Ochs Surveyor's Michigan License N			inhimos Otal D	
•		rorm approved by M	ichigan State Board of Land S	Surveyors, Jan 28, 1971 Revised May 14, 1975
Approved by Peer Review Group o Norman L. Ochs, County Represe	n <u>December 8, 1998</u>	-	THE MANNEY WALL	Revised Jan., 1983
MYO	ILMGYG.	<u> </u>	The state of the s	
11.0.0.		.	NORMAN	į.
		Ž.	L OCHS 🖈	ž