MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COURT REGISTER OF DEEL LINDA H. SROWN

'98 MAR 6 PM 12

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

of min Bu

For corners in Newaygo (County)	Located in:	Carner Code#) -	under III. Q
1. Public Land Survey	T <u>14N</u> R <u>11W</u> T R T R T R	A-2	vol. 2	1i 4
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp &	File Number
4. Lot No, Reco			A B C D E F G H	I J K L M
I, Norman L. Ochs	, in a field survey on <u>October</u> uirements of P. A. 74, Michigan P.	r16 , 19 <u>97 ,</u> A of 1970 the corner	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
points mentioned in lines 1 and therefore as required in the curr Department of the Interior, Bure	2 above were in conformance with rent manual of survey instructions au of Land Management or by a	regulations and rules of the United States decree of a Court of	5 - 18 - 17 - 16 - 15	+ 14 + 13 -
conformance with the rules of	oints mentioned in lines 3, 4 and the Michigan Board of Land olished, re-established, monument pelow:	Surveyors or by a	7 8 - 19 - 20 - 21 - 22 9	23 - 24 -
Note: Not more than 4 recorded on this	corners, all in the same to certificate.	own and range, may be	10 30 + 29 + 28 + 27	+++
West One Quarter Corner, S	Section 6, Goodwell Township	, Newaygo County, Michigan.	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	$T^{3}T^{3}$

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1838 8" Sugar S21°W 6 Links (3.96')#1 40" Black Oak N21°W 12 Links (7.92')#2

Lyle Shepherd R.L.S. #503 Witness Book Number 1 Page 5 Book 36 Pages 90 and 91 September 6, 1916 Found old stake. 30" Pine Stump N371/2°W 37.5'± #3 4" Twin White Oak S671/2°W 42.51± #4

Ronald J. Ruszala R.L.S. #21581 LCRC #369 November 25, 1975 Set 1" Pipe using Government notes, no landmarks present. 20" Twin Maple S89°W 50.12' Set nail and blaze at base. 12" Maple N41°W 70.12' Set nail and blaze. Northwest leg of tower #4194 S66°E 37.0' at base.

OVER &

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 3 foot threaded 3/2" Pipe with coupling, 21/2" Bolt screwed into end with 1" nut held on by Bolt. The centerline of the North and South Power line two-track is 81 feet East. The centerline of overhead wires are 43 feet East. The East edge of North and South woods line is 45 feet West. The condition of the recorded witnesses are: #1 thru #4 gone, #5 thru #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Pipe and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

17"-20" Forked Maple (blazed) N87°W 50.13' Found spike in Southeast side of tree and set spike and tag above it. #5 18" Maple (blazed) N38°W 70.07' Found spike in Southwest side of tree and set spike and tag above it. #6 Northwest leg of Electric Tower #4194 S62°E 37.05' #7

20" Maple (blazed) \$58°W 63.22' Found spike in North side of tree and set spike and tag above it. #8

November 11, 1997

the maple (shallow)			
Signed by Manage L. Ochs	Date November 10, 1997		
Norman L. Ochs			
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971		
	Revised May 14, 1975		

Revised Jan., 1983



n, L. O.

Approved by Peer Review Group on _

Norman L. Ochs, County Representative.

A. Description (cont.)

Alan L. Meyer R.L.S. #15406 LCRC #998 February 1990 22" Twin Maple West 50.20' Nail and blaze. #5 16" Maple N40°W 70.0' Nail and blaze. #6 Northwest leg of Tower #4194 S66°E 37.0' at base. #7 18" Maple S45°W 63.16' Nail in Westerly root. #8