SURVEY & TON

MAR 0 2 1999

1998 Newaygo County Remonumentation Project REGISTER OF DEEDS

NEWAYGO COUNTY

FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '99 FEB 17 PM 3 42

· ·	FILING REQUIR	(FINEIGI OF MCC 14) missing		Л
SECTION For corners in Newaygo	Located in:	Corner Code #	Linsa M.	. Brown
(County) 1. Public Land Survey	T_14N R_11W TR TR TR	<u>E-13</u>	vol. 2	268
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp & F	ile Number
4. Lot No, Reco		19.98	$\frac{1}{2} - 6 + 5 + 4 + 3$	+ 2 + 1 + 1 + 11 + 12
points mentioned in lines 1 and therefore as required in the CD Department of the Interior. But the comer that the comer	, in a field survey on Augustiquirements of P. A. 74, Michigan I 2 above were in conformance warrent manual of survey instruction read of Land Management of by points mentioned in lines 3, 4 of the Michigan Board of Latablished, re-established, monural below.	into regulations and the control of the United States and 5 above were in and 5 above wore of by a	5 1 1 1 1 1 1 1 1 1	14 + 13 -
Note: Not more than recorded on thi	4 corners, all in the sam s certificate.	e town and range, may be	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	- - - - -
Southwest Corner, Section	on 33, Goodwell Township, N	lewaygo County, Michigan.	DIOR SUBSEQUENT REST	ORATION:

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1837 24" Pine N34°W 6 Links (3.96')#1 12" Pine N67°E 38 Links (25.08')#2 Closing Corner of Sections 4 and 5, T13N R11W is West 40 Links (26.40')#19

Ralph A. Smith R.L.S. #3421 1950's Approximate Corner Book 46A Page 9 12" Maple Northeast 53.5' #9 Telephone Pole Southeast 29.5' #10 8" Black Oak Southwest 63.5' #11 15" Black Oak Northwest 59.0' #12

Newaygo County Road Commission Sheet Power Pole Southeast 40.5' #3 6" Poplar South 39.5' #4

Newaygo County Road Commission iron Power Pole S43°E 114.7' #5 8" Black Oak N40°W 104.6' #6 U.S.G.S. Monument N37°E 76.7' #7 Project Marker S48°W 56.5' #8

OVER \$

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING

Found 5" X 5" Concrete Monument with brass plate 1 foot ± below grade (also 5" dock spike over concrete monument). The centerline of the North and South bituminous road is 26 feet ± West and the centerline of the East and West bituminous road is 1 foot ± North. The condition of the recorded witnesses are: #1 thru #14 gone, #15 and #16 good condition, #17 and #18 gone, #19 and #20 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 5" X 5" Concrete Monument with brass plate as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Accepted 5" X 5" Concrete Montanto A the original corner. careful and faithful reestablishment of the original corner.	
Power Pole N15°E 90.31' Found spike with tag #13584 in Wes "X" on top centerline of concrete project marker (3'± tall) S63°I	n cast iron monument in monument box
16" White Oak (blazed) N47 Cons	Date October 20, 1998
Norman L. Ochs Surveyor's Michigan License No. <u>22439</u>	Form approved by Michigan State Board Land Sulveyin Jan 283 1877 Revisel May 14, 1975 ** RANB Jan., 1983 SURVEYOR ** SURVEYOR **
Approved by Peer Review Group on November 10, 1998 Norman L. Ochs, County Representative.	22439

n. L.O.

A. Description (cont.)

Robert A. Griffin R.L.S. #13584
1972 Found Iron Pipe at intersection
Power Pole N25°E 97.95' Tag in Northwest side. #13
Project Marker S46°W 56.84' #8
Telephone Pole N66°W 82.77' Tag in Southwest side. #14

Robert A. Griffin R.L.S. #13584

LCRC #220 1972 Found the Iron (by Patrick Salisbury). Replaced (in the exact location) the Iron with a 5" square reinforced concrete post 3 feet in length having a 3" diameter brass disk.

Power Pole N10°E 90.25' #15

"X" cut in the top center of a concrete project marker S60°W 78.20' #16

Telephone Pole N72°W 107.38' #17

Northeast Corner, Section 32, T14N R11W N00°16'55'W 5325.48'

Patrick A. Salisbury R.L.S. #13594 LCRC #354 October 16, 1974 Found Iron set 5" square monument Power Pole N10°E 90.25' #15 Project Marker S60°W 78.20' #16 Telephone Pole N72°W 107.38' #17

Patrick R. Leemon R.L.S. #31595
October 29, 1985 Recorded in Liber 349 Page 8318
5" X 36" Concrete
10" White Oak N44°E 84.87' #20
Power Pole N10°E 90.25' #15
Project Marker S60°W 78.20' #16
Telephone Pole N72°W 107.38' #17
Northeast Corner, Section 5, T13N R11W West 26.40' #19

William Byl, Inc.
Found P.K. nail February 1988
Power Pole S33°E 97.26' #18
"X" top of concrete right of way marker S60°W 78.26' #16
Power Pole Southeast 98.25' #18
P.K. at Northeast Corner, Section 5, T13N R11W West 26.27' #19
Power Pole N10°E 90.42' #15

Stephen Vallier R.L.S. #28428
Job Number WS-91-0880 September 12, 1991 Found P.K. nail
P.K. Nail at Northeast Corner, Section 5, T13N R11W West 26.27' #19
Power Pole S33°E 97.26' #18
"X" in top of concrete right of way marker S60°W 78.26' #16
Power Pole N10°E 90.42' #15
16" White Oak N44°E 84.90' #20

SURVEY & REMONUMENTATION

MAR 0 2 1999

SECTION