SURVEY & REMONUMENTATION

MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYSS COURTY REGISTER OF DEEDS LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAR 6 PM 12 36

Newaygo (County)	Located in:	Corner Code#	Lin	aam. C
1. Public Land Survey	T <u>14N</u> R <u>12W</u> T R T R T R	<u>C-1</u>	vol. $oldsymbol{2}$	109
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp & File	Number
do hereby certify that under req points mentioned in lines 1 and a therefore as required in the curr Department of the Interior, Bure Law and/or that the corner po conformance with the rules of Decree of a Court of Law; estat recovered, found as expressed to	, in a field survey onDecemb uirements of P. A. 74, Michigan P./ 2 above were in conformance with reent manual of survey instructions of eau of Land Management or by a points mentioned in lines 3, 4 and the Michigan Board of Land blished, re-established, monument below: corners, all in the same to	A. of 1970, the corner regulations and rules of the United States decree of a Court of 5 above were in Surveyors or by a red, re-monumented,	A B C D E F G H I 2 - 6 - 5 - 4 - 3 - 3 4 - 7 - 8 - 9 - 10 - 5 6 - 18 - 17 - 16 - 15 - 7 8 - 19 - 20 - 21 - 22 - 9 10 - 30 - 29 - 28 - 27 - 11	14 - 13 -
Northwest Corner, Section 5	5, Wilcox Township, Newaygo (County, Michigan.	12 31 + 32 + 33 + 34 +	35 + 36

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1837 8" White Oak S20°E 20 Links (13.2')#1 36" Pine S66°W 24 Links (15.84')#2

Delos G. Anderson (County Surveyor) January 29, 1900 Book A Pages 289 and 290 Old Government Corner Pine Witness there

Ralph A. Smith R.L.S. #3421 November 1963 Witness Book Number 1 Page 15 Book 88 Page 26 Set 3/4" Pipe 12" Red Oak S62°E 24.2' #3 12" Red Oak N10°E 37.1' #4 5" White Oak N42°W 34.9' #5 16" White Oak S35°W 24.5' #6

Clinton E. Cole R.L.S. #17615 File Number 2300-74 November 5, 1974 Gives no witnesses.

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 3/4" X 22" Iron Pipe (pinched on bottom) with cap #17615 in centerline of the East and West dirt road and in centerline of two-track going South. The remnants of fence going South is 15 feet East. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 3/4" Iron Pipe and set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner. 16" Red Oak (blazed) S60°E 24.20' Set spike and brass washer in North side of tree. #3 20" Red Oak (blazed) N12°E 37.72' Set spike and brass washer in West side of tree, #4 10" White Oak (blazed) N42°W 34.90' Set spike and brass washer in Northeasterly side of tree, #5 10" White Oak (blazed) S35°W 24.90' Set spike and brass washer in Northwesterly side of tree. #6 Southwest Corner, Section 32, T15N R12W, 4" Harrison Monument West 29.05" Ks 10man Signed by Date <u>December 15, 1997</u> Norman L. Ochs Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Surveyor's Michigan License No. 22439

December 18, 1997

Revised May 14, 1975 Revised Jan., 1983



