MAR 1 9 1998

1997 Newaygo County Remonumentation Project

SECTION LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGU COUNTY REGISTER OF DEEDS LINDA M. BROWN

'98 MAR 6 PM 12 3

For corners in Newaygo	Located in:	Corner Code#	P.	da M. Os
(County)			Qu:	an M. Ou
1. Public Land Survey	T <u>14N</u> R <u>12W</u> T R T R	<u>E-1</u>	YOL. 2	112
Property Controlling in Section	TR STR STR		100.	J. J. A
Miscellaneous Property in Sec.	STR STR	Reg	ister of Deeds Stamp & F	ile Number
4. Lot No, Reco			A B C D F F G H 2 6 5 4 3 3	I J K L M
do hereby certify that under rec points mentioned in lines 1 and therefore as required in the cur Department of the Interior, Burn Law and/or that the corner po conformance with the rules o	, in a field survey on <u>December</u> puirements of P. A. 74, Michigan P. A. 2 above were in conformance with rest manual of survey instructions deau of Land Management or by a coints mentioned in lines 3, 4 and f the Michigan Board of Land blished, re-established, monument below:	A. of 1970, the corner regulations and rules of the United States decree of a Court of 15 above were in Surveyors or by a ed, re-monumented,	5 6 - 18 - 17 - 16 - 15 - 7 8 - 19 - 20 - 21 - 22 - 9	23 - 24 -
Note: Not more than 4 recorded on this	corners, all in the same to certificate.	wn and range, may be	10 30 + 29 + 28 + 27 - 11 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 +	7 26 + 25 - + 35 + 36 -
Northeast Corner, Section 5	5, Wilcox Township, Newaygo C		13	
A. DESCRIPTION OF O	RIGINAL MONUMENT ANI	D ACCESSORIES AND/OR	SUBSEQUENT RESTOR	RATION:
G.L.O. John Hodgson 8" Beech S78°W 48 Link 10" Hemlock S72°E 14 L	s (31.68')#1 inks (9.24')#2	East 6.61' #4	nd ¾" Pipe ction 32, T15N R12W, (¾"	Pipe)
Delos G. Anderson (Cou Book A Pages 289 and 2 16" Tamarack N04°W 98	90 January 29, 1900	30" Maple S08°W 19.5 15" Red Oak S84°W 4		
Ralph A. Smith R.L.S. #3 October 1963 Survey of	421 f North One Half of Northeas	st Quarter of Section 5, T14h	N R12 W , shows corner ar	nd no witnesses.
	V			OVER %
B. DESCRIPTION OF C REESTABLISHING COF	ORNER EVIDENCE FOUNI RNER:	D AND/OR METHOD APPL	IED IN RESTORING OR	
	pe. The centerline of the Ea e condition of the recorded v			
C. DESCRIPTION OF M THE POSITION OF THE	ONUMENT FOR CORNER CORNER:	AND ACCESSORIES ESTA	ABLISHED TO PERPET	JATE LOCATING
	d set a 4" diameter Harrison e section corner and is acce			
36" Maple (blazed) S12°\ 24" Black Oak (blazed) S 8"-8" Twin Cherry (blazed 16" Red Oak N72°W 56.8 Power Pole S45°W 91.12	on 32, T15N R12W, 4" diame W 19.52' Found spike in We i86°W 41.95' Found nail and d) N66°W 27.61' Found spik i88' Found nail and tag #3038 2' Found spike in Northerly si	st side of tree. #5 I tag #30389 in South side of e in Northerly side of tree. #3 89 in South side of tree. #8	f tree. #6	
Signed by // Signed by Norman L. Ocl	* / 	Date <u>December</u>	r 15, 1997	
Surveyor's Michigan License		Form approved by Mich	igan Set Board of Land Survey	sed May 14, 1975
Approved by Peer Review Group Norman L. Ochs, County Repres			NORMAN L: OCHS	evised Jan., 1983
11.9.0.		₹ * [LAND	

A. Description (cont.)

Carl P. Englert Jr. #18987
May 16, 1994 Found Pinch Pipe
Recorded in Liber 360, Page 5889
Twin Oak S80°W 42.07' #6
36" Maple South 19.58' #5
Twin Cherry N70°W 27.62' #7
1" Pipe East 6.61' (Southeast Corner, Section 32, T15N R12W) #4

William Fries Jr. R.L.S. #30389 Undated Survey 1" Pinch pipe 30" Maple S08°W 19.56' #5 15" Black Oak S64°W 19.56' #6 10" Oak N72°W 57.00' #8 1¼" Pipe West 6.61' (Southeast Corner, Section 32, T15N R12W) #4