

WAR 6 2 1999

### 1998 Newaygo County Remonumentation Project

### LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'99 FEB 17 PM 3 42

#### SECTION

For corners in  Newaygo (County)	Located in:	Corner Code#	d	nda M. Brown
Public Land Survey	T <u>14N</u> R <u>12W</u> T R T R	<u>J-13</u>	vol. 2	260
Property Controlling     in Section     Miscellaneous     Property in Sec.	STR STR STR STR		Register of Deeds St	amp & File Number
4. Lot No, Reco	rded Plat		A B C D E F 2 - 6 - 5 - 4 3	G H I J K L M
do hereby certify that under rec points mentioned in lines 1 and therefore as required in the cur	in a field survey on October uirements of P. A. 74, Michigan P. 2 above were in conformance with rent manual of survey instructions au of Land Management or by a	regulations and rules of the United States decree of a Court of	5 1	6 + 15 + 14 + 13 -
and among with the rules of	oints mentioned in lines 3, 4 ar f the Michigan Board of Land blished, re-established, monumer below:	Office Anto of the	$   \begin{array}{c cccccccccccccccccccccccccccccccccc$	22 + 23 + 24 + 25 + 25 + 25 + 25 + 25 + 25 + 25
recorded on this			$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	33 + 34 + 35 + 36 -
South One Quarter Corner	Section 35, Everett Township	o, Newaygo County, Michigan	). 13 <del>-   -   -   -   -   -   -   -   -   - </del>	

### A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1837 14" Black Ash N27°E 37 Links (24.42')#1 10" Black Ash N15°W 26 Links (17.16')#2

Steve Vallier R.L.S. #28428

March 27, 1985 Found ¾" Iron in the centerline of Baseline Road and Thornapple
8" Poplar S20°E 48.0' #6
30" Stump S45°W 41.5' #4
6" Poplar S50°W 45.1' #7
Telephone Riser N40°E 42.6' #8

Newaygo County Road Commission Sheet Iron 16" Pine S71°VV 85.00' #3 20" Elm S44°E 40.5' #4 12" Maple S51°E 51.95' #5

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found  $\frac{3}{4}$ " X 24" Rerod next to a 5/8" X 26" Steering Shaft (with 4" long tie Rod attached). The centerline of the East and West bituminous road is 1 foot North and the centerline of the gravel road going North is 3 feet West. The condition of the recorded witnesses are: #1 and #2 gone, #3 stump, #4 thru #6 gone, #7 good condition, #8 gone.

# C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rerod and steering shaft and set a 2¾" X 20" Harrison cast iron monument marked "County Survey" in a new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

		MINISTER STATES
16" Stump S71°W 85'± to centerline. #3 12" Ash (blazed) S50°W 45.21' Set spike with tag #22439 in North One Quarter Corner, Section 2, T13N R12W, West 16 14" Aspen (blazed) N18°E 83.45' Found spike with tag #3036 26" White Pine (blazed) N18°W 111.22' Set spike with tag #2006	.98' 89 in Northwesterly side of tree. 22439 in East side of tree.	NORMAN  L. OCHS  LAND SURVEYOR  No.
10" Elm (blazed) S13°E 48.12' Set spike with tag #22439 in	yvest side of tree.	22439
Signed by Holman L. Ochs	Date November 3, 1998	TO LAND
Norman L. Ochs		MANAMAS SALL
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board	Revised May 14, 19/5
Approved by Peer Review Group on December 8, 1998 Norman L. Ochs, County Representative.		Revised Jan., 1983
11.40		