MAR 6 2 1999

## 1998 Newaygo County Remonumentation Project

**NEWAYGO COUNTY** REGISTER OF DEEDS LINDA M. BROWN

**SECTION** 

LAND CORNER RECORDATION CERTIFICATE '99 FEB 17 PM 3 39 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in  Newaygo  (County)	Located in:	Corner Code #	Linda M. Da	our!
Public Land Survey	T <u>14N</u> R <u>13W</u> T <u>14N</u> R 14W TR TR	A-8 M-8	YOL. <b>2</b>	24
2. Property Controlling in Section	STR STR		•	
Miscellaneous     Property in Sec.	STR STR		Register of Deeds Stamp & File Nur	nber
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curricular that the curricular that the corner possible to the	, in a field survey onFebrualizements of P. A. 74, Michigan P. 2 above were in conformance with ent manual of survey instructions au of Land Management or by a ints mentioned in lines 3, 4 are the Michigan Board of Land dished, re-established, monumentalished, re-established, re	A. of 1970, the corner regulations and rules of the United States a decree of a Court of ad 5 above were in Surveyors or by a nted, re-monumented,	5 6 -18 - 17 - 16 - 15 - 14 - 7 19 - 20 - 21 - 22 - 23 - 9 10 - 30 - 29 - 28 - 27 - 26 -	- 24 -
recorded on this c		Name of the second of the seco	11 12 - 31 - 32 - 33 - 34 - 35 -	36 -
	Section 19, Lincoln Township, orner - Section 24 -		ewaygo County, Michigan.	لـــــــــــا
			OR SUBSEQUENT RESTORATION	N:

G.L.O. Mullett and Brookfield 1838 7" Beech S48°W 23 Links (15.18')#1 8" Beech N33°W 40 Links (26.4')#2

Newaygo County Road Commission Sheet 1/2" Iron Power Pole N22°E 117.2' #3 Fence Post S86°E 24.7' #4

Norman L. Ochs R.L.S. #22439 Drawing Number 92415B Power Pole N22°E 117.65' #3 Fence Post S88°E 24.47' #4 Fence Post S88°W 33.82' #8 14" - 14" Twin Cherry S20°E 112.34' #7 George Blass R.L.S. #5489 LCRC #278 June 23, 1961

Found 5/8" Iron reinforcing Rod in gravel road North and South in line with very old fences East and West 3 feet East of centerline of road North and South from witnesses of Newaygo County Road Commission.

Set 6" diameter by 5 foot long reinforced Concrete Monument 16" White Oak N05°E 186.00' #5

22" Twin Red Oak N88°E 236.15' #6

8" Triple White Cherry S10°E 110,86" #7

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR **REESTABLISHING CORNER:**

Found 1" diameter X 8" Rod over 3" diameter brass cap in 6" concrete cylinder and the centerline of the North and South road is 3.5 feet West. The fence line going East is 3 feet South and on field line going West. The condition of the recorded witnesses are: #1 and #2 gone, #3 and #4 good condition, #5 stump, #6 thru #8 good condition.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rod and set a 23/4" X 20" Harrison cast iron monument marked "County Survey" over concrete cylinder as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Power Pole N26°E 117.55' Found spike in West side of pole. #3
Fence Post S82°E 24.54' Found spike in South side of post. #4
16" Stump N11°E 186.3' to center. #5
22" - 38" Twin Red Oak S88°E 237.68' Set spike with tag #22439 in South side of tree. #6
16" - 21" White Cherry S05°E 112.28' Middle of both trees found spike in West side of tree. #7
Fence Post S88°W 33.92' Found spike in south side of post. #8
$\mathscr{Y}_{\infty}$ $\mathscr{S}_{\alpha}$ $\mathscr{S}_{\alpha}$
Signed by 10man L. Ocho Date November 5, 1998
Norman I Ochs

Form approved by Michigan State Board of Land Surveyor Lives

Surveyor's Michigan License No. 22439

Approved by Peer Review Group on \_ November 10, 1998 Norman L. Ochs, County Representative.

Revised May 14, 1975 Revised Jan., 1983

MICHIGA

**NORMAN** L. OCHS LAND SURVEYOR

11.2.0