MAY 28 1997

1996 Newaygo County Remonumentation Project

REGISTER OF DEEDS LINDA M. BROWN

NEWAYGO COUNTY

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

0

For corners in Newaygo (County)	Located in:	Corner Code #		Tinds!	M. Osowa
1. Public Land Survey	T <u>15N</u> R <u>11W</u> T <u>16N</u> R <u>11W</u> T R T R	<u>C-13</u>	vol. 2	PAGE	23
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		gister of Deeds	Stamp & Fil	e_Numb'er
				DEFG	
do hereby certify that under req points mentioned in lines 1 and therefore as required in the cur Department of the Interior, Bure Law and/or that the corner po conformance with the rules of Decree of a Court of Law; estat recovered, found as expressed in	, in a field survey onMay 17_ uirements of P. A. 74, Michigan P.A. 2 above were in conformance with rent manual of survey instructions of eau of Land Management or by a soints mentioned in lines 3, 4 and the Michigan Board of Land olished, re-established, monumentatelow.	a. of 1970, the corner egulations and rules of the United States decree of a Court of 5 above were in Surveyors or by a ed, re-monumented,	2 3 4 5 6 10	5 -	3 2 12 13 15 14 13 172 21 24 15 172 24 172 24 173 172 173 172 173
Note: Not more than 4 recorded on this	corners, all in the same t certificate.	own and range, may be	12	32]
	n 6, Norwich Township, Ne on 31, Barton Township, Ne				·

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1838 11" Beech S41°W 43 Links (28.38')#1 7" Cedar S28°E 26 Links (17.16')#2

Delos G. Anderson (County Surveyor) 1898 Reported distance of 2624.16' West to North One Quarter Corner, Section 6

Duane F. Wood L.S. #24625 1988 Set ½" Rod in intersection of roads at split of right-of-way fences LCRC #829 Triple Cedar AZ 163° 58.8' #3 6" Birch AZ 205° 69.2' #4 8" Poplar AZ 320° 46,4' #5

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found Duane F. Wood's ½" Rebar and accessories 4 and 5 that fit the corner. I measured 2643.21 feet West to the North One Quarter Corner of Section 6 and 2635.12 feet South to the East One Quarter Corner, Section 6 and 2636.95 feet East to the North One Quarter Corner of Section 5. Accessories 1, 2 and 3 were gone. Corner is in centerline of East and West gravel road and 4 feet West of centerline of road to the South.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed ½" Rod and set 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

8" White Birch \$18°W 69.05' Spike in East side of tree. #4	•
11" Poplar N40°W 46.60' Spike in Southwest side of tree. #5	
Power Pole \$26°E 43.95' Found P.K. nail in Northeast side of pole.	
Power Pole N41°E 39.02' Found P.K. nail in Southeast side of pole.	
10" Cedar N43°W 84.46' Spike in Southwest side of tree.	,
Signed by Marman L. Ochs	Date September 12, 1996
700	Date
Surveyor's Michigan License No. 22420	Forms announced by Millianian Office Donald Ch. 10

Approved by Peer Review Group on <u>October 24</u>, <u>1996</u>
Norman L. Ochs, County Representative.

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975 Revised Jan., 1983



M. L.O.