

MAR 1 3 2000

## NEWAYGO COUNTY REGISTER OF DEEDS 1999 Newaygo County Remonumentation Project LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATION FEB 28 PM 1 17

	TILINO REGUIT		•	
For corners in Newaygo (County)	Located in:	Corner Code#	Linda M. L	nacion
1. Public Land Survey	T <u>15N</u> R <u>11W</u> T R T R T R	<u>L-7</u>	' VOL. 2	359
Property Controlling in Section     Miscellaneous Property in Sec.	STR STR STR		Register of Deeds Stamp & F	ile Number
4. Lot No, Rec 5. Private Claims			A B C D E F G H 2 - 6 - 5 - 4 - 3 3	1 J K L M 2 + 1 -
do hereby certify that under repoints mentioned in lines 1 and therefore as required in the cu Department of the Interior, Bu Law and/or that the corner conformance with the rules Decree of a Court of Law, esta recovered, found as expressed.		A, of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a ted, re-monumented,	5 6 - 18 - 17 - 16 - 15 7 8 - 19 - 20 - 21 - 22 9	23 - 24 -
recorded on this		•	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	╬╼┼╼┼╼┼╼┤
	, Section 24, Norwich Township ORIGINAL MONUMENT AN		OR SUBSEQUENT RESTO	RATION:
G.L.O. Milton Nye 18 9" Beech N59½°W 43 L	56 Resurvey inks (28.38')#1	Duane F. LCRC #96	Wood R.L.S. #24625 65 December 4, 1986 Concrete Monument	
of G.L.O. No occupation N60°±E 43' of corner. 12" Red or Black Oak N	.S. #13594 Pipe with cap by prorate n. Found forest service tag Corner is ± 684' South of M- 110°±E 33.55' #3 (probably i	16" Oak Now 12" Oak State 12"	112°W 33.65' #6 55°E 42.75' #5 572°W 4.40' #4 Ochs R.L.S. #22439 27, 1976 Drawing Number ete monument	76002B
	lack Oak S80°±W 4.49' #4 r Black Oak N60°±E 42.72' i	#5 12" - 10" ·	0ak N10°E 33.55' #3 Twin Red Oak S80°W 4.49' # Red Oak N60°E 42.72' #5	OVER 🤄
B. DESCRIPTION OF C	ORNER EVIDENCE FOUNI	O AND/OR METHOD AF	PLIED IN RESTORING OR	REESTABLISHING
Found 4" diameter cond is no other apparent oc	crete monument and the cer cupation. The condition of th	nterline of the East and W e recorded witnesses ar	/est quad (4 wheel) trail is 8 te: #1 and #2 gone, #3 thru #6	feet ± South. There 5 good condition.
C. DESCRIPTION OF THE POSITION OF TH		R AND ACCESSORIES	ESTABLISHED TO PERPE	TUATE LOCATING
Accepted 4" diameter of faithful reestablishmen	concrete monument as a su t of the position of the origina	bstantial marker for the al corner.	quarter corner and is accept	ed as a careful and
14" - 12" Red Oak S60 8" - 8" - 8" Triple Red O	3.59' Found spike in East sic °W 4.43' Found spike in Nor Oak N60°E 42.65' Found spil .63' Set spike with tag #224	th side of tree, #4 se in South side of tree. #		
Signed by Norman L. C	y L. Ochs	DateNo	ovember 8, 1999	
Surveyor's Michigan Licer	nse No. <u>22439</u>	Form approved t	oy Michigan State Roard of Land Sun Re	wised May 14, 1975
Approved by Peer Review Gr Norman L. Ochs, County Rep	oup on <u>December 16, 1999</u> presentative.	_ <del></del>	NORMAN	Revised Jan., 1983
11. L.O.			L. OCHS	

## A. Description (cont.)

Jack E. Pierson R.L.S. #19305
June 29, 1976 Recorded in Series I, Number 1623 and Series H, Number 5143
Concrete monument
16" Oak N12°W 33.65' #6
8" Oak N65°E 42.75' #5
12" Oak S72°W 4.40' #4

SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION