MAR 1 9 1998

1997 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE 4, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA H. BROWN

'98 MAR 6 PA 12 38

SECTION	LITIMA KEGOIKEMEN I	01 Act 74	1
•			

Newaygo Located in: C	Forner Code#	u M. Breeze
1. Public Land Survey T_15N R_12W T R T R T R 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R		133
Property in Sec. STR	Register of Deeds Stamp & Fil	e Number
4. Lot No, Recorded Plat 5. Private Claims i, Norman L. Ochs, in a field survey on	the corner s and rules ted States a Court of were in s or by a numented,	- 2 - 1 - - 11 - 12 - - 14 - 13 -
Note: Not more than 4 corners, all in the same town and recorded on this certificate.	range, may be 10 30 + 29 + 28 + 27 + 11	26 - 25 -
Southwest Corner, Section 32, Monroe Township, Newaygo County	/, Michigan.	35 + 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1837 28" Black Oak N17°E 25 Links (16.5')#1 15" White Oak N24°W 30 Links (19.8')#2

Patrick A. Salisbury R.L.S. #13594

1973 Set 5/8" Rerod by G.L.O. distance from Section Corner of 5 and 6, T14N R12W

20" Black Oak N10°W 41.93' #3

14" Black Oak N45°W 64.03' #4

12" Black Oak S15°W 45.42' #5

Northwest Corner, Section 5, T14N R12W (¾" X 18" Pipe) East 29.04' #6

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ¾" X 19" Rerod in the centerline of the East and West dirt road and in line with fence going North. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 3/2" Rerod and set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section comer and is accepted as a careful and faithful reestablishment of the original corner.

26" Black Oak N07°W 41.93' Set spike and brass washer in East side of tree. #3

20" Black Oak (with two blazes) N41°W 64.03' to centerline. #4

18" Black Oak (blazed) S15°W 45.42' Set spike and brass washer in West side of tree above old spike mostly overgrown. #5 Northwest Corner, Section 5, T14N R12W, 4" diameter Harrison monument East 29.05' #6

16" Red Oak (blazed) S75°E 51.88' Set spike and brass washer in North side of tree.

20" Red Oak (blazed) N45°E 50.75' Set spike and brass washer in West side of tree.

10" White Oak (blazed) N14°E 26.63' Set spike and brass washer in Northeasterly side of tree.

22" White Oak (blazed) S33°E 24.37' Set spike and brass washer in Northwesterly side of tree

\mathcal{N}	$\varphi \propto 0$	and the state of the control of the		
Signed by / Ohman	d. Ochs	Date	December 15, 1997	
Norman L. Ochs	3		December 15, 1997	
Commence of the commence of				

Surveyor's Michigan License No. 22439

Form approved by Michigan State and of Land Surveyors, Jan 28, 1971

Approved by Peer Review Group on ___December 18, 1997 Norman L. Ochs, County Representative.



Revised May 14, 1975 Revised Jan., 1983