MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MRR 6 PM 12 38

For corners in Newaygo (County)	Located in:	Corner Code #	J.	ada M. Brewn
Public Land Survey Property Controlling	T_15N R_12W TR TR TR STR	D-13	vol. $oldsymbol{2}$	135
in Section 3. Miscellaneous Property in Sec.	STR STR		egister of Deeds Stamp &	k File Number
4. Lot No, Rec. 5. Private Claims, Rec. 5. Private Claims, Rec. 6. Private Claims	4 corners, all in the same tov	or 1970, the comer gulations and rules the United States ecree of a Court of 5 above were in surveyors or by a d, re-monumented,	2 - 6 - 5 - 4 - 3 - 4 - 7 - 8 - 9 - 5 - 6 - 18 - 17 - 16 - 7	22 - 23 - 24 - 1 - 1 - 1 - 27 - 26 - 25 - 1 - 1 - 1 - 1 - 1
South One Quarter Corne	er, Section 32, Monroe Township, i	Newaygo County, Michigar	n. ₁₃	11111

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

8" Pine N27°E 13 Links (8.58')#1 14" Aspen N59°W 27 Links (17.82')#2

Delos G. Anderson (County Surveyor) Book A Page 289 and 290 January 29, 1900 Old Corner and Witness of Government Survey found.

Patrick A. Salisbury R.L.S. #13594 1973 Found 3/4" X 18" Pipe Power Pole S60°E 41.13' #6 24" Black Oak N40°W 81.34' #7 6" White Oak S35°W 74.53' #8

Ralph A. Smith R.L.S. #3421 Book 88 Page 21 April 17, 1958 Set 3/4" Pipe 12" Black Oak S85°E 69.50' #3 4" White Oak N10°W 60.00' #4 10" Poplar S30°E 52.30' #5

Newaygo Engineering and Survey Company August 23, 1977 Found 3/4" Pipe North One Quarter Corner, Section 5, Wilcox Township, East 11.86' #9 Power Pole S58°E 41.13' #6 16" Black Oak N35°W 81.30' #7 8" White Oak \$38°W 74.53' #8

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ¾" Iron Pipe in centerline of gravel road going North and in centerline of gravel road going East. The centerline of gravel road going South is 5 feet East and the centerline of gravel road going West is 16 feet South. The condition of the recorded witnesses are: #1 and #2 gone, #3 and #4 stump, #5 gone, #6 thru #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 3/2" Pipe and set 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

marker 10) the 35025. Commercial transfer and the second s	
Power Pole \$53°E 41.03' Found spike in North side of pole. #6 30" White Oak (blazed) N32°W 81.29' Found spike and tag #22439 in Westerly 16" White Oak (blazed) \$42°W 74.30' Found spike and tag #22439 in Northwes 16" White Oak (blazed) N55°E 97.50' Found spike and tag #22439 in Northwest North One Quarter Corner, Section 5, T14N R12W, East 11.85'	felly side of a co. we
Date Decemb	er 17, 1997
Signed by Date December Norman L. Ochs Surveyor's Michigan License No. 22439 Form approved by Michigan License No. 22439	higan State Board of land

Approved by Peer Review Group on <u>December 18, 1997</u>
Norman L. Ochs, County Representative.

M. L. O.