MAR 1 3 2000

NEWAYGO COUNTY REGISTER OF DEEDS

1999 Newaygo County Remonumentation Project LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATED FEB 28 PM 1 17. FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	orner Code#	Linda M. E	Brown
1. Public Land Survey	T_15N R_12W T R T R	J-11	' vol. 2	361
Property Controlling in Section Miscellaneous	STR STR			
Property in Sec.	\$TR	R	egister of Deeds Stamp & F	ile Number
to he buy certify that under req points mentioned in lines 1 and : therefore as required in the curr Department of the interior, Bure Law and/or that the corner po conformance with the rules of	_, in a field survey on , in a field survey on), the corner s and rules ited States a Court of s were in	5	2 - 1 -
Note: Not more than 4 or recorded on this c	corners, all in the same town and ertificate.	range, may be	10 30 + 29 + 28 + 27	26 - 25 -
	Section 35, Monroe Township, Newayg	o County, Michigan.	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	35 + 36 -
A. DESCRIPTION OF OR			47	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye 1856 Resurvey 10" Hemlock N62°E 44 Links (29.04')#1 12" Hemlock S28°W 28 Links (18.48')#2

1913 W. Willits (Michigan State Highway Department) Monument - Station 125 + 16.0 plans 9G-19 Circle on plans only

Norman L. Ochs R.L.S. #22439 September 1989 8" White Pine N25°E 38.68' #7 4" White Pine N45°W 26.10' #8 12" - 10" Twin Maple N05°W 65.49' #6 10" White Pine S70°W 26.24' #9 Ralph A. Smith R.L.S. #3421 January 3, 1958 Book 88, page 20 Corner Fence Post North 29.5' #3 5" Poplar N45°W 22.1' #4 West Post of sign S03°E 106.7' #5 8" Twin Maple N05°W 65.0' #6

Norman L. Ochs R.L.S. #22439
August 4, 1980 Drawing Number 80116F
Found %" Pipe
8" White Pine N25°E 38.71' #7
4" White Pine N45°W 26.17' #8
12" - 10" Twin Maple N05°W 65.48' #6
Corner Fence Post North 29.85' #3
West Post of sign S03°E 106.75' #5

OVER &

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1½" Pipe with brass cap 1 foot below grade and in the centerline of the bituminous road going South and in the centerline of the bituminous road going East and on line ± with fence going West and old corner fence post North. The condition of the recorded witnesses are: #1 and #2 gone, #3 found fence post North 29.5' (decomposed), #4 gone, #5 good condition, #6 gone, #7 thru #10 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 1½" Pipe with brass cap as a substantial marker for the quarter corner and is accepted as a careful and faithful reestablishment of the original corner.

West leg Curve Sign S06°E 106.20′#5 20″ White Pine N15°E 38.66′ Found spike in Westerly side of 16″ White Pine N60°W 26.00′ Set spike and tag #22439 in Sc 14″ White Pine S65°W 26.21′ Reset spike and tag #22439 in 16″ Ash N37°W 41.12′ Found spike in Westerly side of tree. # Carsonite Post North 1′	outherly side of tree. #8	NORMAN L. OCHS LAND SURVEYOR
Signed by // Signed by Norman L. Ochs	Date <u>October 22, 1999</u>	22439 SIN
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of	Land Surveyors Jan 28, 1971
Approved by Peer Review Group on <u>December 16, 1999</u> Norman L. Ochs, County Representative.		Revised May 14, 1975 Revised Jan., 1983

A. Description (cont.)

Corey J. Hughes R.L.S. #20706 LCRC #1178 June 1992 Found ¾" Pipe, Set 1½" Pipe and brass cap 12" White Pine S74°30'W 26.23' #9 12" Ash N25°W 41.10' #10 12" White Pine N58°W 26.12' #8 14" White Pine N18°E 38.65' #7

SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION