MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '98 MIR 6 PM 12 37

For corners in Newaygo	Located in:	Corner Code #	Lines W	, d
(County)			Chuan III	· Openun
Public Land Survey	T <u>15N</u> R <u>14W</u> T R T R T R	1-3	vol. $oldsymbol{2}$	119
Property Controlling in Section	STR STR			
3. Miscellaneous	STR			
Property in Sec.	STR		Register of Deeds Stamp & Fil	e Number
4. Lot No, Recor	ded Plat		ABCDEFGHI	JKLM
5. Private Claims			1	111
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burea Law and/or that the corner pois conformance with the rules of Decree of a Court of Law; establi recovered, found as expressed be Note: Not more than 4 c recorded on this ce	orners, all in the same tovertificate.	of 1970, the corner agulations and rules of the United States decree of a Court of 5 above were in Surveyors or by a ad, re-monumented, wn and range, may be	5	23 - 24 -
Southeast Corner, Section 3,	Beaver Township, Newaygo C	County, Michigan.	13	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1857 40" White Pine N791/2°E 21 Links (13.86')#1 14" Beech S661/2°E 31 Links (20.46')#2 16" Beech N65°W 52 Links (34,32')#3

Newaygo County Road Commission Sheet 1" Iron 14" Red Pine S58°W 73.6' #4 12" Red Pine S08°E 67.0' #5 Power Pole N61°E 60.1'#6

Delos G. Anderson (County Surveyor) Book A Page 216 September 14, 1897 **Old Government Corner**

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found large amount of discolored sand, pieces of deteriorated metal, 1/2" X 6" Rerod (mostly deteriorated) 18" below surface, went down 4 feet and found nothing else in the centerline of the East and West bituminous road. The centerline of two-track going North is 4 feet West. The centerline of two-track going South is 15 feet West. Fence line going South is 30 feet West. The condition of the recorded witnesses are: #1 thru #3 gone, #4 dead, #5 stump, #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed deteriorated metals and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

18" Red Pine (dead) S60°W 73.6' to face. #4				
18" Red Pine Stump S07°E 66.6' to face. #5				
Power Pole N63°E 60.35' Set spike and tag in South side of pole. #6				
8" Red Pine (blazed) S06°E 40.42' Set spike and tag in East side of tree.				
24" Red Pine (blazed) S26°W 90.30' Set spike and tag in East side of tree.				
Power Pole N13°W 96.84' Set spike and tag in East side of pole.				
α				
Signed by Lormon Z. Ocho Date November 10, 1997				
Marman I Ocho				

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975

Approved by Peer Review Group on November 11, 1997
Norman L. Ochs, County Representative.

22439

Surveyor's Michigan License No.



