## **SURVEY &** REMONUMENTATION

MAR 1 9 1998

1997 Newaygo County Remonumentation Project

**'98** MRR 6 PM 12 37

33 + 34 + 35

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

Linds M. Bown

NE D COUNTY REGISTER OF DEEDS

LINDA M. BROWN

**SECTION** 

For corners in Newaygo (County)	Located in:	Corner Code#	·	
I. Public Land Survey	T <u>15N</u> R <u>14W</u> T R T R T R	<u>K-7</u>	vol. $oldsymbol{2}$	124
2. Property Controlling in Section	STR STR STR			
3. Miscellaneous Property in Sec.	s TR		Register of Deeds Stamp & F	ile Number
do hereby certify that under re- points mentioned in lines 1 and therefore as required in the cu Department of the Interior, Bur Law and/or that the corner p conformance with the rules of	, in a field survey on <u>Novemb</u> quirements of P. A. 74, Michigan P. d 2 above were in conformance with irrent manual of survey instructions reau of Land Management or by a points mentioned in lines 3, 4 an of the Michigan Board of Land ablished, re-established, monumer	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a	A B C D E F G H  2 - 6 - 5 - 4 - 3  3 - 1 - 1 - 1  4 - 7 - 8 - 9 - 10  5 - 18 - 17 - 16 - 15  7 - 1 - 1 - 15  9 - 19 - 20 - 21 - 22  9 - 1 - 1 - 1	- 14 - 13 - - 23 - 24 -
Note: Not more than 4 recorded on this	corners, all in the same to certificate.	own and range, may b	be $10 - 30 + 29 + 28 + 27$	726 + 23 1

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1857 10" Maple N391/2°E 9 Links (5.94')#1 18" Hemlock N68°W 20 Links (13.20')#2 12" White Pine S19°E 15 Links (9.90')#3

Northwest Corner, Section 24, Beaver Township, Newaygo County, Michigan.

Newaygo County Road Commission Sheet

5" Pine Stake

4" Spruce N45°W 51.6' #6

5" Spruce \$40°W 35.7' #7

Lyle S. Shepherd R.L.S. #503 July 15, 1917 Book 5 Pages 32 and 51 40" Pine Stump N161/2°E 431/2 Links (28.71')#4 20" Pine Stump S75°W 26 Links (17.16')#2

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 3" X 3" X 18" Pointed Wood Post (burnt on the pointed end) 8" below grade in the centerline of the North and South two-track. Remnants of right-of-way fences on East and West side of two track. The condition of the recorded witnesses are: #1 thru #5 gone, #6 and #7 good condition.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed pointed wood post and set a 4" Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and falthful reestablishment of the original corner.

12" Jack Pine N37°W 51.6' to center. #6		-			
14" Jack Pine S50°W 35.7' to center. #7					
8" Jack Pine (blazed) N45°E 25.32' Set spike and brass was	sher in Westerly side of tree.				
10" Jack Pine (blazed) S80°E 31.80' Set spike and brass washer in North side of tree.					
18" Jack Pine (blazed) S22°W 62.37' Set spike and brass washer in East side of tree.					
16"-16" Twin Black Oak (blazed) S88°W 107.40' Set spike a	and brass washer in South side of tree	<b>a</b> .			
	ally plass waster in court side of the	<b>.</b>			
Signed by Morman L. Ochs	Date <u>December 15, 1997</u>				
Norman L. Ochs					
Surveyor's Michigan License No. 22439 Form approved by Michigan State Board of Land Surveyors, Jan 2					
		Revised May 14, 1975			
Language Barriery Oreum on Becomber 19, 1007	air Air British College	Revised Jan., 1983			

December 18, 1997 pproved by Peer Review Group on Norman L. Ochs, County Representative.

