

MAY 28 1997

COMMISSION

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 **'97 FEB 1**2 'PM 4 45

For corners in Newaygo (County)	Located in:	Corner Code#		Ginda	m. B	التلايف
Public Land Survey Property Controlling	T <u>16N</u> R <u>11W</u> T R T R T R S T R	C-9	vol. 2	PAGE	35	
in Section	STR					
Miscellaneous Property in Sec.	STR S T R		gister of Deeds	Stamp & File	<u>Number</u>	
			A B	chat	G # 1 J	KLM
4. Lot No, Records. Private Claims	ded Plat		2			- - -
•	•		3	-	 	- - -
Norman L. Ochs ,	in a field survey on Decemb	er 17 , 19 96 ,	<u> </u>	~ - -		2-
do hereby certify that under requ	irements of P. A. 74, Michigan P above were in conformance with	A. of 1970, the corner	5	- -	! 	
therefore as required in the curr	ent manual of survey instructions	of the United States	6 18-		- 15 14	1 3
Department of the Interior, Bure	au of Land Management or by a	a decree of a Court of	7 -	-	- 	_ _ _
Law and/or that the corner po	ints mentioned in lines 3, 4 ar the Michigan Board of Land	nd 5 above were in	5 19.		22 23	J
Decree of a Court of Law estab	ine Michigan Board of Land lished, re-established, monume	nted. re-monumented.	9 _	_		_ _ _
recovered, found as expressed below:			10 20	2020	1 1 1	,_ _ ,_
Note: Not more than 4 recorded on this		town and range, may be	1:	- - - -		
Northwest Comer Section	n 20 Porton Townshin N	lewayae County Michigan				

Northeast Comer, Section 30, Barton Township, Newaygo County, Michigan

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1856 15" Hemlock N68°E 22 Links (14.52')#1 14" Sugar S15°W 34 Links (22.44')#2

Delos G. Anderson (Co. Surveyor) Book A Page's 177 & 178 September 1895 Old corner gas pipe about 6 feet East of culvert #3

Robert L. Wetherell RLS #24624 September 16, 1989 See file Number 533-89 Found 1/2" Iron marker L.S. 10688 10" Cherry N70°W 116.75' #7 Power Pole S50°W 39.97' #5 14" Maple N66°E 70.12'#8 1/2" Iron South 33.00' #9

Clayton S. Hay RLS #10688 September 23, 1982 LCRC #551 Found 3/" Iron in road bed down 18", set rerod and cap over iron Corner fence post N15°E 26.80' #4 Power Pole S45°W 40.00' #5 4" White Cherry N45°E 39.08' #6

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR **REESTABLISHING CORNER:**

Found 1/2" pipe over 1/2" iron and the centerline of the East and West road is 4 feet South and there is a fence going North that is 10 feet East of corner and the condition of the recorded witnesses are: #1 thru #3 gone, #4 and #5 good condition, #6 gone, #7 thru #9 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 1/2" pipe and 1/2" iron and set a 4" Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Square Spike Corner fence post N15°E 26.92' Spike in West side of	of post.#4
Power Pole S50°W 39.95' Spike in Northwest side of pole. #5	
10" Cherry N70°W 116.81' Spike in Southwest side of tree. #7	
14" Maple N66°E 70.12' Spike in Southeast side of tree. #8	'
½" Iron with cap #24624 South 33.00' #9	•
\mathcal{M} \mathcal{M} \mathcal{M} \mathcal{M} \mathcal{M}	•
Signed by //Brnow & Ocho	Date <u>December 20, 1996</u>
Norman L. Ochs	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
	Revised May 14, 1975
Approved by Peer Review Group On	Revised Jan., 1983

Approved by Peer Review Group On _ December 23, 1996

Norman L. Ochs, County Representative.

