MAY 2 8 1997

COMMISSION

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'97 FEB 12 PM 4 45

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	Corner Code #		Linda)	n. Brown
1. Public Land Survey	T <u>15N</u> R <u>11W</u> T <u>16N</u> R <u>11W</u> T R T R	C-1	VOL. $oldsymbol{2}$	PAGE	23
 Property Controlling in Section Miscellaneous Property in Sec. 	STR STR STR STR	Re	gister of Deeds	Stamp & File	Number
4 Lathle D			<u> ۲ تا ۸</u>	U E F G I	
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burea Law and/or that the corner poi conformance with the rules of Decree of a Court of Law; establic recovered, found as expressed by Note: Not more than 4 of the point of the corner of the co	_ , in a field survey onMay 17 irements of P. A. 74, Michigan P. above were in conformance with ant manual of survey instructions au of Land Management or by a nts mentioned in lines 3, 4 and the Michigan Board of Land ished, re-established, monumentelow:	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a	7	5	
recorded on this		·	1231	32	
Northeast Comer, Section Southeast Comer, Section	ı 6, Norwich Township, Ne n 31, Barton Township, Ne	ewaygo County, Michigan ewaygo County, Michigan			7
A. DESCRIPTION OF O	RIGINAL MONUMENT A	ND ACCESSORIES AND/C	R SUBSEQU	ENT RESTO	RATION:
G.L.O. John Hodgson 1838 11" Beech S41°W 43 Links (2	28.38')#1	Delos G. Anderson (Cour		t to North One	Ougstar

7" Cedar S28°E 26 Links (17.16')#2

ist to North One Quarter Corner, Section 6

Duane F. Wood L.S. #24625 1988 Set ½" Rod in intersection of roads at split of right-of-way fences LCRC #829 Triple Cedar AZ 163° 58.8' #3 6" Birch AZ 205° 69.2' #4 8" Poplar AZ 320° 46.4' #5

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found Duane F. Wood's ½" Rebar and accessories 4 and 5 that fit the corrier. I measured 2643.21 feet West to the North One Quarter Corner of Section 6 and 2635.12 feet South to the East One Quarter Corner, Section 6 and 2636.95 feet East to the North One Quarter Corner of Section 5. Accessories 1, 2 and 3 were gone. Corner is in centerline of East and West gravel road and 4 feet West of centerline of road to the South.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 1/2" Rod and set 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

8" White Birch S18°W 69.05' Spike in East side of tree. #4 11" Poplar N40°W 46.60' Spike in Southwest side of tree. #5 Power Pole S26°E 43.95' Found P.K. nail in Northeast side of pole. Power Pole N41°E 39.02' Found P.K. nail in Southeast side of pole. 10" Cedar N43°W 84.46' Spike in Southwest side of tree. Signed by //Aman C

September 12, 1996

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975 Revised Jan., 1983

Approved by Peer Review Group on <u>October 24, 1996</u>
Norman L. Ochs, County Representative.

