MAR 1 3 2000

NEWAYGO COUNTY

1999 Newaygo County Remonumentation Project EGISTER OF DEEDS

LINDA M. BROWN

SECTION

FILING REQUIREMENT of Act 74, Mich. P.A. 19700 FEB 28 PM 1 18

Newaygo (County)	Located in:	Corner Code #	Linds M. B	rown
1. Public Land Survey	T <u>16N</u> R <u>11W</u> T R T R	<u> -3</u>	, VOL. 2	374
2. Property Controlling in Section	STR STR			0.1
Miscellaneous Property in Sec.	STR STR		Register of Deeds Stamp & File	Number
do hereby certify that under req points mentioned in lines 1 and: therefore as required in the cur Department of the Interior, Bure Law and/or that the corner po conformance with the rules of	, in a field survey onJuly 9 uirements of P. A. 74, Michigan P.A 2 above were in conformance with re- rent manual of survey instructions of sau of Land Management or by a co- plints mentioned in lines 3, 4 and f the Michigan Board of Land of blished, re-established, monuments	a. of 1970, the corner egulations and rules of the United States decree of a Court of 5 above were in Suppovers or by a	A B C D E F G H I 2 - 6 - 5 - 4 - 3 3 - 1 - 1 - 10 5 - 18 - 17 - 16 - 15 7 - 19 - 20 - 21 - 22 9 - 1 - 1 - 1	
Note: Not more than 4 a recorded on this o	corners, all in the same to certificate.	wn and range, may be	10 - 30 + 29 + 28 + 27 +	-+
Northwest Corner, Section 1	1, Barton Township, Newaygo	County, Michigan.	12 31 + 32 + 33 + 34 +	35 + 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye 1856 Resurvey 4" Hemlock N52°E 51 Links (33,66')#1 8" Yellow Birch S671/2°W 53 Links (34,98')#2

Delos G. Anderson (County Surveyor)
Book A, Page's 279 and 280 January 4, 1900
Old Corner

James J. Keller R.L.S. #10693
August 9, 1989 Recorded in Liber 349, Page 1596
Found Iron in monument box
Power Pole N52°W 36.75' #8
Sign Post 2" Pipe N45°E 34.65' #9
Consumers Power Company Pole S55°E 103.95' #10
15" Cherry S14°E 91.00' #11

11.4.0

Lyle S. Shepherd R.L.S. #503 November 19, 1915 Book B, Page's 72 and 73 and Book 96, Page 13 Steel shaft and glass, etc. Southeast Corner Store N33°W 121 Links (79.86')#3 16" Aspen N42½°E 70 Links (46.2')#4

Newaygo County Road Commission Sheet Gas Pipe in monument box 10" Hemlock N55°W 84.0' #5 Concrete Slab S40°W 73.0' #6 30" Poplar N45°E 45.9' #7

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1" \times 20" Rod, 5/8" \times 20" Rod in monument box and found crockery in hole. The centerline of the North and South bituminous road is 1 foot \pm North and the centerline of the East and West bituminous road is 3 feet \pm South. The condition of the recorded witnesses are: #1 thru #8 gone, #9 thru #11 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rods and set a 2%" diameter Harrison cast iron monument 18" long marked "County Survey" in monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

2" Pipe Sign Post N40°E 34.58' #9			4	OF MICH	Market .
Power Pole S60°E 103.95' Found spike in North side of pole.	.114.0		3		1.4
18" Cherry S20°E 91.00' Found spike in Southwest side of tre	#1U 		\$ ~ /	NORMAN	1.1
Southeast Corner of Building N55°W 84.15'	· • · · · · · ·		# * i	L OCHS	14
Signed by Morman L. Ocho	Date	October 22, 1999		SURVEYOR No.	15
Norman L. Ochs		October 22, 1999	- 4	22439	1
Surveyor's Michigan License No. 22439	Form appro	ved by Michigan State Board	of Land Su	evois, tabled,	U TE
Approved by Peer Review Group on November 30, 1999			Re	VISCHIER CO.	975
Norman L. Ochs, County Representative.				Revised Jan., 1	983