

MAR 0 2 1999

#### 1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

SECTION LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3 43

I. Norman L. Ochs , in a field survey on December 15 , 19 98 , do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented,	For corners in Newaygo (County)	Located in:	Corner Code#	Lind	es M. Brown
in Section  S_T_R  Broperty in Sec.  S_T_R  Property in Sec.  S_T_R  Register of Deeds Stamp 8  4. Lot No, Recorded Plat  5. Private Claims  INorman L_Ochs, in a field survey onDecember 15, 19_98, do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented,	Public Land Survey		E-11	YOL. <b>2</b>	274
I. Norman L. Ochs , in a field survey on December 15 , 19 98 , do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented,	in Section 3. Miscellaneous	TR TR TR		Register of Deeds Sta	mp & File Number
Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	I, Norman L. Ochs do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burea Law and/or that the corner poil conformance with the rules of Decree of a Court of Law; establistecovered, found as expressed between the Note: Not more than 4 c	eld survey on <u>December</u> nts of P. A. 74, Michigan P. A. 94, Michigan P. A. 94, Michigan P. A. 94, Michigan B. 94, Michigan Board of Land Michigan Board of Land 1, re-established, monument ers, all in the same to	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a reed, re-monumented,	1	3 - 2 - 1 - 10 - 11 - 12 - 15 - 15 - 14 - 13 - 1 - 22 - 23 - 24 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -

#### A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Thomas Whelpley Resurvey 1856 18" Hemiock N58°E 29 Links (19.14')#1 34" Hemlock S63°W 32 Links (21.12')#2

Lyle S. Shepherd R.L.S. #503 Book B, Page 62 and 63 April 27, 1915 Found old stake (cedar post) Iron Witness Post S45°W 47.0' #3

Newaygo County Road Commission Sheet Buggy Axle 6" Pine S54°E 55.59' #5 Power Pole S26°E 87.69' #9 Corner Post S47°W 42.7' #10 6" Red Pine N44°E 73.10' #4 William B. Batzer R.L.S. #13026 1965 Found Iron Pipe at intersection 4" Pine N44°E 78.06' #4 8" Pine S52°E 56.06' #5 5" Cedar Post N45°E 46.7' #6

Undated notes from the Newaygo County Road Commission Buggy Axle Stake Southwest 47.0' #3 Pine Stump Northeast 95.0' #7 Pine Stump Southeast 82.9' #8

OVER &

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 5" square concrete monument with brass disk in monument box on line with the centerline of the North and South dirt road and the centerline of the East and West bituminous road is 1 foot ± North. The condition of the recorded witnesses are #1 thru #3 gone, #4 and #5 good condition, #6 lying down, #7 and #8 gone, #9 good condition, #10 gone, #11 did not verify, #12 good condition.

# C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 5" square concrete monument with brass disk in monument box as a substantial marker for the is accepted as a careful and faithful reestablishment of the original corner.  14" Red Pine (blazed) N44°E 78.17' Found cabin spike in Southeast side of tree. #4 16" Red Pine (blazed) S50°E 56.05' Set spike with tag #22439 over nail in Northeast side of tree. #5 Power Pole S23°E 88.07' Found spike with tag #13584 in Northeast side of pole. #9 Power Pole S33°W 86.00' Found spike with tag #22439 in Southeast side of pole. #12  Signed by	
16" Red Pine (blazed) S50°E 56.05' Set spike with tag #22439 over nail in Northeast side of tree. #5 Power Pole S23°E 88.07' Found spike with tag #13584 in Northeast side of pole. #9 Power Pole S33°W 86.00' Found spike with tag #22439 in Southeast side of pole. #12  Signed by	he section corner and
Norman L. Ochs	NORMAN  * L. OCHS  LAND  SURVEYOR
Surveyor's Michigan License No22439 Form approved by Michigan State Board of Land Surveyor's Michigan State Board of La	<b>%</b> - 22439

### A. Description (cont.)

Robert A. Griffin R.L.S. #13584
August 20, 1969 LCRC #203
Found an Iron Pipe at the intersection of roads North, South, East and West. Replaced with a 5" square reinforced concrete monument 3 feet in length with brass disk.
4" Red Pine N44°E 78.09' #4
4" square X 7' Treated Pine Post S45°E 46.69' #6
8" Red Pine S52°E 56.03' #5
Center of the concrete monument marking the South One Quarter Corner, Section 28, East 2655.00' #11
Power Pole S26°E 88.14' #9

Norman L. Ochs R.L.S. #22439 1986 Found big spike over concrete monument 4" Red Pine N44°E 78.09' #4 8" Red Pine S52°E 56.03' #5 Power Pole S26°E 88.10' #9

Norman L. Ochs R.L.S. #22439
July 15, 1997 Drawing Number 97165B
Found 5" concrete monument with brass disk
12" Red Pine S52°E 55.98' #5
Power Pole S24°E 88.10' #9
Power Pole S32°W 85.98' #12
10" Red Pine N43°E 78.10' #4



SURVEY & REMONUMENTATION

MAR 02 1999

SECTION