

MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE '97 FEB 12 PM 4 45

2. Property Controlling S T R S INScellanous S INSC	W. W. Vissen Same	FILING REQUIR	REMENT of Act 74, Mic	:h. P.A. 1970	0 TV 111	
1. Public Land Survey  T 16N R 14W T 15N 140 T R T R T R T R T R T R T R T R T R T R	Newaygo	Located in:	Corner Code#	Lin	da M. E	Ground
in Section  STR  Property in Sec.  Property in Sec.  STR  Register of Deeds Stamp & File Number  Property in Sec.  STR  Register of Deeds Stamp & File Number  Register of Dee	1. Public Land Survey	T 15NR 14W T R R T R		vol. $oldsymbol{2}$	PAGE	50
Property in Sec.    Recorded Plat	in Section	S T R				
4. Lot No	= :					
do hereby cetify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lires 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of LauM analogement or by a decree of a Court of Law, established, re-established, monumented, re-monumented, re-		ed Plat		2	5	
recorded on this certificate.  South One Quarter Corner, Section 34, Troy Township, Newaygo County, Michigan North One Quarter Corner, Section 3, Beaver Township, Newaygo County, Michigan A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION G.L.O. Thomas Whelpley Resurvey 1856 8" Fir N29"E 12 Links (7.92")#1 10" Herdlock N09"W 23 Links (15.18")#2  Delos G. Anderson (County Surveyor) Book A Page 216 September 14, 1897 24" Pine Stump S39"E 23 Links (15.18")#3  County Surveyor Witness Book Page 136 16" Pine Stump N02½"W 30.7 #4 20" Pine Stump N02½"W 30.7 #4 20" Pine Stump N14½"E 51.6"#6  B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:  Found a corner fence post with a fence running South on ground and East and West on ground with posts fallen down. Also four running North 16.8 feet West. The fence line running South best fit the prorated distance between the found Southeast Corner of 34 and the found Southwest Corner of Section 33. The only known corners on the township line. Also I feel that the fence running south best fit only Surveyor, therefore, I held the fence post for common One Quarter Corner position and measured 2636.30 feet from the Southwest Corner to the South One Quarter Corner to the South One Qu	do hereby certify that under require points mentioned in lines 1 and 2 a therefore as required in the current Department of the Interior, Bureau Law and/or that the comer point conformance with the rules of to Decree of a Court of Law; establis	ements of P. A. 74, Michigan P., bove were in conformance with a manual of survey instructions of Land Management or by a sementioned in lines 3, 4 and the Michigan Board of Land hed, re-established, monument	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a	0 10		0 11 1 5 14 1 2 
South One Quarter Corner, Section 34, Troy Township, Newaygo County, Michigan North One Quarter Corner, Section 3, Beaver Township, Newaygo County, Michigan A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION G.L.O. Thomas Whelpley Resurvey 1856  6" Fir N29"E 12 Links (7.92)#1  10" Hemlock N09"W 23 Links (15.18")#2  Delos G. Anderson (County Surveyor)  Book A Page 216 September 14, 1897  24" Pine Stump 939"E 23 Links (15.18")#3  County Surveyor Witness Book Page 136  16" Pine Stump N02½"W 30.7" #4  20" Pine Stump N02½"W 30.7" #4  20" Pine Stump N17½"E 42.8" #5  16" Pine Stump N44½"E 51.6" #6  B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:  Found a corner fence post with a fence running South on ground and East and West on ground with posts fallen down. Also four running North 16.8 feet West. The fence line running South best fit the prorated distance between the found Southeast Corner of 34 and the found Southeast Corner of Section 33. The only known corners on the township line. Also I feet that the fence running was probably placed there as a result of the 1897 survey by Delos Anderson, County Surveyor, therefore, I held the fence post for common One Quarter Corner position and measured 2593.30 feet from the Southwest Corner of the South One Quarter Corner to the Southwest Corner of the Found Southeast Corner of the South one Quarter Corner are measured 2593.91 feet from the South One Quarter Corner to the Southwest Corner of her south one Politic of the record witnesses are: #1 thru 6 gone. The land in this corner vicinity has been plowed or planted to pines North and South of the fence.  C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:  Set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner accepted as a careful and faithful reestablishment of the original corner.			town and range, may	be 11 ——————————————————————————————————	)2	]
A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION G.L.O. Thomas Whelpley Resurvey 1856 8" Fir N29"E 12 Links (7.92"#1 10" Hemlock N09"W 23 Links (15.18"#2  Delos G. Anderson (County Surveyor) Book A Page 216 September 14, 1897 24" Pine Stump S39"E 23 Links (15.18"#3  County Surveyor Witness Book Page 136 16" Pine Stump N02%"W 30.7 #4 20" Pine Stump N02%"W 30.7 #4 20" Pine Stump N44%"E 51.6' #6  B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:  Found a corner fence post with a fence running South on ground and East and West on ground with posts fallen down. Also four running North 16.8 feet West. The fence line running South best fit the prorated distance between the found Southeast Corner of 34 and the found Southwest Corner of Section 33. The only known corners on the township line. Also I feel that the fence running was probably placed there as a result of the 1897 survey by Delos Anderson, County Surveyor, therefore, I held the fence post for common One Quarter Corner position and measured 2636.30 feet from the Southwest Corner to the South One Quarter Corner as measured 2639.11 feet from the South One Quarter Corner to the Southwest Corner of Section 34 and the condition of the record witnesses are: #1 thru 6 gone. The land in this corner vicinity has been plowed or planted to pines North and South of the fence.  C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:  Set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner accepted as a careful and faithful reestablishment of the original corner.	South One Quarter Comer	Section 34, Troy Towns	ship, Newaygo County, Beaver Township, N	Michigan	ichigan	
8" Fir N29"E 12 Links (7.92"#1 10" Hemlock N09"W 23 Links (15.18"#2  Delos G. Anderson (County Surveyor) Book A Page 216 September 14, 1897 24" Pine Stump S39"E 23 Links (15.18"#3  County Surveyor Witness Book Page 136 16" Pine Stump N02½"W 30.7 #4 20" Pine Stump N02½"W 30.7 #4 20" Pine Stump N17½"E 42.8" #5 16" Pine Stump N44½"E 51.6" #6  B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:  Found a corner fence post with a fence running South on ground and East and West on ground with posts fallen down. Also four running North 16.8 feet West. The fence line running South best fit the prorated distance between the found Southeast Corner of 34 and the found Southwest Corner of Section 33. The only known corners on the township line. Also I feel that the fence running was probably placed there as a result of the 1897 survey by Delos Anderson, County Surveyor, therefore, I held the fence post for common One Quarter Corner position and measured 2636.30 feet from the Southwest Corner to the South One Quarter Corner a measured 2639.11 feet from the South One Quarter Corner to the Southeast Corner of Section 34 and the condition of the record witnesses are: #1 thru 6 gone. The land in this corner vicinity has been plowed or planted to pines North and South of the fence.  C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:  Set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner accepted as a careful and faithful reestablishment of the original corner.  8" Jack Pine South 107.81" Tag and nail in East side of tree.	<u>•</u>					ATION:
Book A Page 216 September 14, 1897 24" Pine Stump S39°E 23 Links (15.18')#3  County Surveyor Witness Book Page 136 16" Pine Stump N02½"W 30.7 #4 20" Pine Stump S17½"E 42.8' #5 16" Pine Stump N44½"E 51.6' #6  B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:  Found a corner fence post with a fence running South on ground and East and West on ground with posts fallen down. Also four running North 16.8 feet West. The fence line running South best fit the prorated distance between the found Southeast Corner of 34 and the found Southwest Corner of Section 33. The only known corners on the township line. Also I feel that the fence running was probably placed there as a result of the 1897 survey by Delos Anderson, County Surveyor, therefore, I held the fence post for common One Quarter Corner position and measured 2636.30 feet from the Southwest Corner to the South One Quarter Corner a measured 2639.11 feet from the South One Quarter Corner to the Southeast Corner of Section 34 and the condition of the record witnesses are: #1 thru 6 gone. The land in this corner vicinity has been plowed or planted to pines North and South of the fence.  C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:  Set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner accepted as a careful and faithful reestablishment of the original corner.  8" Jack Pine South 107.81' Tag and nail in East side of tree.	8" Fir N29°E 12 Links (7.92')#	1	,			
16" Pine Stump N02½"W 30.7" #4 20" Pine Stump N17½"E 42.8" #5 16" Pine Stump N44½"E 51.6" #6  B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:  Found a corner fence post with a fence running South on ground and East and West on ground with posts fallen down. Also four running North 16.8 feet West. The fence line running South best fit the prorated distance between the found Southeast Corner of 34 and the found Southwest Corner of Section 33. The only known corners on the township line. Also I feel that the fence running was probably placed there as a result of the 1897 survey by Delos Anderson, County Surveyor, therefore, I held the fence post for common One Quarter Corner position and measured 2636.30 feet from the Southwest Corner to the South One Quarter Corner a measured 2639.11 feet from the South One Quarter Corner to the South one Quarter Corner and witnesses are: #1 thru 6 gone. The land in this corner vicinity has been plowed or planted to pines North and South of the fence.  C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:  Set a 4" claimeter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner accepted as a careful and faithful reestablishment of the original corner.  8" Jack Pine South 107.81' Tag and nail in East side of tree.	Book A Page 216 September	14, 1897	•			
REESTABLISHING CORNER:  Found a corner fence post with a fence running South on ground and East and West on ground with posts fallen down. Also four running North 16.8 feet West. The fence line running South best fit the prorated distance between the found Southeast Corner of 34 and the found Southwest Corner of Section 33. The only known corners on the township line. Also I feel that the fence running was probably placed there as a result of the 1897 survey by Delos Anderson, County Surveyor, therefore, I held the fence post for common One Quarter Corner position and measured 2636.30 feet from the Southwest Corner to the South One Quarter Corner a measured 2639.11 feet from the South One Quarter Corner to the Southeast Corner of Section 34 and the condition of the record witnesses are: #1 thru 6 gone. The land in this corner vicinity has been plowed or planted to pines North and South of the fence.  C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:  Set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner accepted as a careful and faithful reestablishment of the original corner.  8" Jack Pine South 107.81' Tag and nail in East side of tree.	16" Pine Stump N02½°W 30.7 20" Pine Stump S17½°E 42.8'	" #4 #5	,			
running North 16.8 feet West. The fence line running South best fit the prorated distance between the found Southeast Corner of 34 and the found Southwest Corner of Section 33. The only known corners on the township line. Also I feel that the fence running was probably placed there as a result of the 1897 survey by Delos Anderson, County Surveyor, therefore, I held the fence post for common One Quarter Corner position and measured 2636.30 feet from the Southwest Corner to the South One Quarter Corner at measured 2639.11 feet from the South One Quarter Corner to the Southeast Corner of Section 34 and the condition of the record witnesses are: #1 thru 6 gone. The land in this corner vicinity has been plowed or planted to pines North and South of the fence.  C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:  Set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner accepted as a careful and faithful reestablishment of the original corner.  8" Jack Pine South 107.81' Tag and nail in East side of tree.			IND AND/OR METHOD	APPLIED IN RESTO	RING OR	
LOCATING THE POSITION OF THE CORNER:  Set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner accepted as a careful and faithful reestablishment of the original corner.  8" Jack Pine South 107.81' Tag and nail in East side of tree.	running North 16.8 feet West. 34 and the found Southwest C was probably placed there as common One Quarter Corner measured 2639.11 feet from the	The fence line running Sout forner of Section 33. The or a result of the 1897 survey b position and measured 2630 ne South One Quarter Corn	oth best fit the prorated dist only known corners on the t by Delos Anderson, County 6.30 feet from the Southwa der to the Southeast Cornel	ance between the found township line. Also I feel to Surveyor, therefore, I he est Corner to the South Cor	Southeast Co that the fence old the fence po one Quarter Co ondition of the	rner of Section running South ost for the orner and recorded
accepted as a careful and faithful reestablishment of the original corner.  8" Jack Pine South 107.81' Tag and nail in East side of tree.			ER AND ACCESSORIE	S ESTABLISHED TO	PERPETU	ATE
				as a substantial marker fo	r the section o	orner and is
10" Cherry N86°W 18.41' Tag and nail in North side of tree.  14" Red Pine N32°E 29.82' Tag and nail in East side of tree.  12" Red Pine N87°E 27.83' Tag and nail in North side of tree.	10" Cherry N86°W 18.41' Tag 14" Red Pine N32°E 29.82' Ta 12" Red Pine N87°E 27.83' Ta	and nail in North side of tre ig and nail in East side of tre	ee. ee. ree.	ntember 13 1996		
Norman L. Ochs	Norman L. Ochs	in 22439			and Surveyore	 lan 28 1971
Surveyor's Michigan License No. 22439 Form approved by Mishinger State Board of Land Surveyors, Jan 28, 1 Revised May 14, 1 Revised May 14, 1 Revised Jan., 1 Norman L. Ochs, County Representative.  NORMAN L. OCHS LAND	Approved by Peer Review Group C Norman L. Ochs, County Represe	n September 17, 1996	* Y	NORMAN L. OCHS	Revised M	lay 14, 1975