

MAY 28 1997

COMPANY

1996 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

	FILING REQUIR	REMIENT OF ACT 74, MICH. P.A	4. 1970	'97 FEB 1	2 PM 4
For corners in Newaygo (County)	Located in:	Corner Code#		Livie	m. Bes
1. Public Land Survey	T <u>16N</u> R <u>14W</u> T R T R T R	<u>I-11</u>	vol. 2	PAGE	51
Property Controlling in Section Miscellaneous	STR STR STR				
Property in Sec.	\$,TR	<u>Regi</u>	ster of Deeds_Sta	•	
4. Lot No, Reco	rded Plat		3	F F 9 11	J 1(L M
do hereby certify that under requirements mentioned in lines 1 and 2 therefore as required in the curropepartment of the Interior, Bure Law and/or that the corner poconformance with the rules of	in a field survey on <u>September</u> uirements of P. A. 74, Michigan P. 2 above were in conformance with ent manual of survey instructions au of Land Management or by a sints mentioned in lines 3, 4 and the Michigan Board of Land dished, re-established, monument pelow:	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a	6 - 10 - 17 - 7 - 10 - 20 - 20 - 29 - 29 - 29 - 29 - 29 - 2		
Note: Not more than 4 recorded on this	•	town and range, may be	11 -31 -32	- 3334-	
Northeast Corner, Section	n 34, Troy Township, New	aygo County, Michigan	13		احساساء
A. DESCRIPTION OF C	PRIGINAL MONUMENT A	IND ACCESSORIES AND/OI	R SUBSEQUEN	T RESTORA	ATION:
G.L.O. Thomas Whelpley R 10" Lynn N25°E 71 Links (4 10" Lynn N74°W 47 Links (5 Lyle S. Shepherd's R.L.S. # Field Book 96 Page 4 Basswood Northwest 19.6' # Butternut Northeast 11.5' #4 Elm Southwest 12.9' #5	6.86')#1 31.02')#2 503 Witness Book Number 1 ≴3	Conrad Zimmern Monument - Wel Butternut Northe	Point ast 11.5' #3 2.9' #4	Coundy Road	d Commision
Robert A. Griffin R.L.S. #135 LCRC #208 September 15, Found Well Point and witnes 10" Sycamore S48°E 50.82' 7" Maple N66°W 29.88' #7 20" White Pine N05°W 71.3 7" X 7' Cedar Post North 1.5	1966 sses #3, #4, & #5 and set a 5" #6 5' #8	square concrete post with brass	disk		
B. DESCRIPTION OF C		IND AND/OR METHOD APP	LIED IN RESTO	RING OR	
Found Robert A. Griffin's co thru #5 gone, #6 thru #9 god		disk 1.3 feet above ground and th	e condition of the r	ecorded witne	sses are: #1
C. DESCRIPTION OF N		ER AND ACCESSORIES ES	TABLISHED TO	PERPETUA	ATE
Accepted Robert A. Griffin's reestablishment of the origin		stantial marker for the section col	ner and is accepte	d as a careful	and faithful
14" Maple N66°W 29.88' Sp	7' Spike in West side of tree.				

22439 Surveyor's Michigan License No. Approved by Peer Review Group On <u>September 17, 1996</u>
Norman L. Ochs, County Representative.

Norman L. Ochs

ate Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975 Form approved

Date September 13, 1996

NORMAN L. OCHS LAND SURVEYOR Revised Jan., 1983