MAR 1.1 1999

UBER 19296 PG 536

	was in	1999	[]	BER 192901633	U							1
SECTION For corners in		ION Filing	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970			\$ 7.00 * 2.00	MISCE	LLANEOU UMENTAT	S RECO	RDING		;; ;;;
For co		1	1	Carner Code #		7 Z.VV 17 NFC	98 3:	31 P.N.		RECEIF	า# ปุ๋	
	Oakland (County)	Located in:	Lyon ownship	Corner Code #	I	FAID	,,	RECURIA	n - 0	KLAN)	o conf	ŢŢ
	(,	10	Witomp			G. WILL	IAN CAI	MELL			(Ĩ
1. P	ublic Land Survey	T <u>1N</u> R_	7E_	B-5		CLERK/	REGIST	ROFD	EEDS		•	لس ص
		T R_					A C	omplian T 345, P	ce wun .A. 199	0		Ç
								12.			3	
_						5. 台戸見けり 5.7. 6.3. 3.	VED ON: ND COL	NTY RI	EMONU	JMEN'	FATIO	N
	roperty Controlling	S T R_			_ `		PRES C	ROUP	OMMI	TTEE		
	n Section Niscellaneous	STR_			Re	egister	of Dee	ds Stam	p & Fil	e Nur	nber	
	roperty in Sec.	S T R_ S T R_										
•	roperty in ooo.	· · · · · · · · · · · · · · · · · · ·										
4. 1	ot No	Recorded Plat										
						A	в с	DE	F G	н і	J K	L
						2					_ 2	_ ;
						3	Î	Ĭ	i l	Ĭ	Ī_L	Ì
						4						Ţ
l,	Bruce Antcliff	, in a field survey on _ er requirements of P.A. 74	May Michiga	20 19	<u>98</u> ,	1	-7	1	i]	-12-
go ne	ereby certily that unde anod in lines 1 and 2 at	oove were in conformance w	+ Michigai vith regulat	tions and rules therefore a	as required	5	•					1
in the	current manual of surv	ey instructions of the United	d States D	Department of the interior,	Bureau of	6	-18	17	6	15 	14	— t3-
Land	Management or by a de	ecree of a Court of Law and	or that the	e corner points mentioned	in lines 3,	7	11	1				
4 and	5 above were in contr	ormance with the rules of the established, re-established	ie Michiga d. monur	an Board of Land Surveyo hented ire-monumented	recovered.	8 -	19 	-20	21	22	-23	—24-
	as expressed below:	established, re-establishe	u, monun	terrea, re-monumento,	100010100,	9 -				<u> </u>	1	+
NOTE	•	corners, all in the same	town and	l range, may be recorde	ed	10	30	-292	28	27—	-26	—25-
	on this certificat					" 	+	1 1				\dagger
						12	31	-32	i3:	34	-35	36-
A.	Description of origin	nal monument and acces	sories an	nd/or subsequent restor	ration:	13 📖		_L	1 1	LL.	1 1	
B-5	1816 Holmes	G.L.O.			Set Post							
	N/A N/A	O.C. Tax Maps		N	I/A							
	Found no recorded	information for this corne	∍r.									
B.	Description of corne	er evidence found and/or	method	applied in restoring or	reestablishi	ing cor	ner:					
B-5	Found a 1/2" iron 2.5	5' East of a comer fence ru	ınning No	orth, South and West and	d 50' ± West	t of the	South	end of s	wamp.			
					v				00 F	ILE	L	
								-1	00 r	,		
								- 1	00			
	Measure Fast 2639	9.7' to C-5 (G.L.O. = 2640).O') (O.C	C. Tax Map = 2640.84')				1				
		.9' to A-5 (G.L.O. = 1557										
C.	Description of mon	ument for corner and acc	essories	established to perpetu	ate locatino	g the p	osition	of the o	corner	:		
B-5	Replaced 1/2" iron w	rith a 4" x 36" concrete mo	nument w	vith brass cap stamped "	Oakland Co	unty R	emonu	mentatio	on P.S	. #258	326."	
	PK Nail & Oakland (PK Nail & Oakland (PK Nail & Oakland (Co. Remonumentation Tag S & W, West 2.5'	in S Side in W Side in S Side	e 24" Oak S 75° E 11.20' e 30" Oak (dead) N 19° l e 10" Basswood S 81° W	, E 23.09' I 22.28'		* * * * * * * * * * * * * * * * * * * *	B AN' SUR	RUCE TCLIFF VEYOR No. 826	N.	TOR * *	
		n is accepted by the Contr st available evidence of the			y professior	nal	The state of the s	I REO	A H D	Silve Silve	A TOP OF THE PROPERTY OF THE P	
Signe	SALES	(Lute Oil)		Date	12-10	-98	3	***	4			
ાં આવે	o by			Date _								

EARTH TECH

Surveyor's Michigan License No.

25826