FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

UBER 16874N187

LAND CORNER RECORDATION CERTIFICATE \$ 7.00 MISCELLANEOUS RECORDING

Filing Requirement of Act 74, Mich. P.A. 1970 \$ 2,00 REHON/HENTATION	
For corners in	3 JAN 97 7:36 A.M. RECEIPTH BB PAID RECORDED - DAKLAND COUNTY
Oakland Located In: Corner Code #	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
1. Public Land Survey	Compliance with ACT 345, P.A. 1990
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	APPROVED ON: 7-31-96 TMS OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat A B C D E F G H I J K L M	
5. Private Claims	2 6 5 4 3 2 1
1. <u>Joseph C. Kapelczak</u> , in a field survey on <u>7 February</u> , 1996 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines I and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United Slates Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	
A. Description of original monument and accessories and/or subsequent restoration: 12 31 32 33 34 35 36	
Post set in 1816 G.L.O. survey: N 04 W 4lks,24" Lynn; N 18 W 20	
No LCRC's recorded.	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
Recovered: 1" pipe in monument box 2.00' south of centerline 10	SUHVEY &
Recovered witnesses: S 16 E 50.35' Chiseled cross on north rim telephone manhole	REMONUMENTATION
S 26 W 35.23' PK/washer # 24598 in east side telephone pole S 26 W 35.46' PK nail in west side telephone pole	MAY 2 2 1997
S 68 W 110.28' PK/washer in northwest side 18" Apple	COMMISSION
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
Set 5/8" rerod with O.C. remonumentation brass cap.	J. O.KILL
S 26 W 35.22' PK/remon tag in east side telephone pole S 68 W 110.24' PK/remon tag in northwest side 18" Apple N 82 E 158.31' PK/remon tag in east side power pole N 05 E 31.92' PK/remon tag in south side power pole N 77 W 175.81' PK/remon tag in south side power pole	JOSEPH C. KAPELCZAK PROFESSIONAL SURVEYOR No. 24538
Signed by Jeuph C. Kapelerak	Date
Surveyor's Michigan License No. 24548	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971