

UBER 16982 PG 807

FEB 1 2 97 0 3 5 0 9 2

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			I		HISCE REMON			RDIM	3
					97 9:			RECEI	PT# 59A
	Located in:	Corner Code #		PAID		RECORDE	D - 0/	KLAN	D COUNTY
(county)			ł	LYNN	. ALLEN	, CLERK	/REGIS	iter (OF DEEDS
1. Public Land Survey		D-13		Compliance with ACT 345, P.A. 1990					
	T R		. I	ROVED (12	. 9-	94 r.	3	
	<u>T R</u>			(LAND C	OUNTY				ON
2. Property Controlling S in Section S] K			PEF	R GROU	P COMM	HTTEE		
3. Miscellaneous S	G	· · · · · · · · · · · · · · · · · · ·							
Property in Sec. S	T R		Registe	er of De	eds Sta	mp & F	File Nu	ımbe	r
			<u></u>						
4. Lot No, Records	ed Plat						• "		<i>u</i> .
				A B	CD	€ f T T		† †	ों
5. Private Claims			 	2 } ∳-		┼╌∳╌	 å	╌┼╌╌⋛	
I, Joseph C. Kapelczak	, in a field surv	vey on 7 Febuary ,	19 <u>96</u>	3	++	┪	╅╌╂┈	+ +	┷
do hereby certify that under require	ements of P.A. 74	4, Michigan P.A. of 1970,	, the corner points			├	10-	┼ ─!़	
mentioned in lines I and 2 above were in the current manual of survey instru						╁┼		+	+
Land Management or by a decree of						16-	15-		
3, 4 and 5 above were in conforman	ice with the rules o	of the Michigan Board of La	ind Surveyors or by	7			oxdot		
a Decree of a Court of Law, establis	ihed, re-establishe	ed, monumented, re-monu	mented, recovered,						
found as expressed below:				للاو	Ĩ	<u> </u>	lī	Lï	
NOTE: Not more than 4 cor	ners, all in the	e same town and rai	nge. may be				\prod		
recorded on this certifi				1	- -23 -	28 	27-		25
	_			11	11	11	11	11	11
A. Description of original monum	nent and access	ories and/or subsequent	t restoration:	12 -31-	32 	33-	 34 -	3 9	360
Post in 1815 G.L.O. survey: S	21 E 12lks, 10"	Beech; N 35 E 21lks, 6"	Dogwood.	13 [+	·····		
LCRC L6275 P288 Kattouah 1974 Fd. PK nail. *West 3.25' Fd. iron in mon. be *North 30.10' PK nail in west s	ide 18" Elm	section 5 T1.S,R8.E.)							
Northwest 34.80' PK nail in ea Southwest 31.70' PK nail in w		1	, ·						
B. Description of corner evidence	e found and/or r	method applied in restori	ing or reestablishi	ing corn	er:				
Recovered a PK nail on cente			يشير	ಜನಕಾನಾವಾ ಕಾಣ	meet at see				
Recovered witnesses: S 03 E 54.12' PK nail east side power pole				UAV					
S 03 E 55.13' Nail/tag #16034 N 26 W 35.05' Nail/tag #1603	+ east side powe	er pole "Morele	REMO	MUM	ENTA	TION			
N 51 W 67.60' Nail/tag #1603									
N 51 W 67,61' PK nail south		1 1110	W	1Y 2 2	1997				
*N 03 E 30.04' PK nail west si	ide 14" stump		•						61LE
*West 3.26' Centerline monument box (could not open)				imide	SSIO	M		700	1
*confirms LCR0	C witness							် ^{ည့်})
C. Description of monument for	Corner and acce	essories established to p	erpetuate locatin	a the po	sition o	f the co	orner:	·	
O. Description of monament				اعد		-			
Set 5/8" rerod with O.C. rer	monumentation	brass cap in new monu	ment box.		S OF	MON			
S 06 W 39.61' PK/remon to	ag in east side 1	0" Pine	4	7.7	1094	HC.	1.7	l l	
S 03 E 54.33' PK/remon ta N 26 W 34.94' PK/remon ta N 60 E 74.17' PK/remon ta	ag in east side 2	:6" Maple		LICE	APEL ROFES SURV	CZAK BIONAI EYOR			
				LICERAND	246 246	3. 38	35	•	
Signed by (week) C. A	Kapelera) Da	ate 12/11/96	1	OPER	HOME			
7	1 200	6							
Surveyor's Michigan License No.	. ' <u>497</u>	0 FOI	RM APPROVED BY MICHO	AN STATE	BOARD OF	LAND SUR	REVISED		4, 1975
							ベビソドン	~~~	1003