
FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1983



LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

Filing Requirement of Act 74, Mich. PJ	A. 1970
For corners in	\$ 7.00 MISCELLANEOUS RECORDING \$ 2.00 REMONUMENTATION
Oakland Located In: Corner Code #	19 JUL 95 2:02 P.M. RECEIPT# 71A PAID RECORDED - OAKLAND COUNTY
(county)	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
1. Public Land Survey	Compliance with ACT 345, P.A. 1990
T RTR	APPROVED ON: 7-12-95 Tanks OAKLAND COUNTY REMONUMENTATION
2. Property Controlling S T R	PEER GROUP COMMITTEE
in Section S T R	
Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKL
5. Private Claims	2 6 5 4 9 2 - 2
I, <u>Joseph C. Kapelczak</u> , in a field survey on <u>February 17</u> , 19 <u>95</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corn	ner points
mentioned in lines I and 2 above were in conformance with regulations and rules therefore as in the current manual of survey instructions of the United Slates Department of the Interio	or, Bureau 6 12 17 18 18 18 18 18
of Land Management or by a decree of a Court of Law and/or that the corner points mer lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land 9	ntioned in 1 1 1 1
or by a Decree of a Court of Law; established, re-established, monumented, re-monimecovered, found as expressed below:	umented, 8 19 20 21 22 23 24
	nav he 10 30 29 28 27 28 25
NOTE: Not more than 4 corners, all in the same town and range, mecorded on this certificate.	lay be
A. Description of original monument and accessories and/or subsequent restor Post set 1816 G.O.L. survey; N 78 W 6lks, 3" Beech; N 63 E 10lks, 4" Beech. LCRC L6028 P639 Fouty 1972 Fd. 1"pipe centerline Taft Rd East 51.75' Nail &flag south side power pole West 51.90' Nail &flag south side power pole NE 47.76' Nail & flag west side 12" stump	ration: 12 31 32 33 34 35 38
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered 1/2" rerod cap #24598 in monument box on centerline Taft rd Rrecovered witneses: N 88 W 51.59' Nail south side power pole S 33 E 81.32' PK nail northeast side power pole S 87 E 52.08' PK nail north side telephone pole N 08 W 205.21' PK nail east side power pole S 26 W 159.40' Found 1/2" rerod	
C. Description of monument for corner and accessories established to perpetu Set 5/8" rerod with O.C. remonumentation brass cap replacing 1/2"rerod East 52.15' PK/remon tag north side power pole S 33 E 81.51' PK/remon tag northeast side telephone pole West 52.21' PK/remon tag south side power pole N 08 W 205.31' PK/remon tag east side power pole	ate locating the position of the corner: OF MICHO SEPH C. PELCZAK 24598

Surveyor's Michigan License No.