

LIBER 15528PG 782

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Filing Requirement of Act 74	, Mich. P.A. 1970		
For corners in			NISCELLANEOUS RI 95 2:05 P.M.	CORDING RECEIPT# 71A
Oakland Loc (county)	cated in: Corner Code #	1	. ALLEN, CLERK/RE	
1. Public Land Survey T11	N R8E K-13		REMONUMENTATION  Compliance with  ACT 345, P.A. 1996	
1 T T	_ R R	APPROVED	12 13 50	Tons
2. Property Controlling S T in Section S T 3. Miscellaneous S T Property in Sec. S T	R R R R	Perinter of	ER GROUP COMMI Deeds Stamp & F	
		(Cegister of	Decus otality a l	ile i quiribei
4. Lot No, Recorded P		ه ۸ و	CDEFG	HIJKL
5. Private Claims				
I, Joseph C. Kapelczak	in a field survey on February 23	, 19 <u>95</u>		10-11-12-
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines I and 2 above were in conformance with regulations and rules therefore as required				╁╂┼┼
in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in				·16—1-14—1-13—
lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented,				┩╂┼┼┼
or by a Decree of a Court of Law; est recovered, found as expressed below:	ablished, re-established, monumente	ed, re-monumented, s 19	20 21	22 23 24
•				
NOTE: Not more than 4 corner recorded on this certificate		range, may be		
A. Description of original monument	and accessories and/or subsequ	ent restoration:	32 - 33 -	34 35 36
Post set in 1815 G.O.L. survey by Ale	exander Holmes: N 31 E 36lks, 1 S 45 E 6lks, 6"	0" Beech;		
LCRC L 7000 P 841 Wozniak 1977	LCRC L 11852 Ward 1991	2 P 340		
Fd. monument in mon. box	Fd. 1/2" rerod i	in monument box	4.	
N 36 E 58.40' Nail west face D.E. p *South 55.07' Concrete monument		3' Fd. PK nail northwest : Set 60d nail west face u		
N 35 W 61.72' Center top nut of hy	drant N 55 E 62.92'	Fd.PK nail southeast faction of the content of the content of the content on the	ce utilty pole	
B. Description of corner evidence for	und and/or method applied in res	toring or reestablishing co	orner:	
Recovered 1/4" rerod in concrete me Recovered witnesses:	onument in monument box at cen	terline 8 Mile & Meadowt	orook Rds.	
*S 52 W 52.71' PK northwest side p S 52 W 53.01' PK tag #WCR north	west side power pole			
S 04 W 51.58' Nail w/washer west: *S 06 W 55.13' Found monument	side power pole			
S 27 E 75.78' PK tag #WCR west s	side power pole		٠.	00°
N 40 E 71.16' PK tag #WCR northy	west side power pole			./.
N 34 E 68.37' Fd. monument N 15 W 80.09' PK tag #WCR north	east side power pole			
N 23 W 68.91' Fence corner	•	<b> ⁴</b>		
C. Description of monument for corr	* Confirms LCRC ner and accessories established to		position of the co	MICHICA
Set 5/8" rerod with O.C. Remonume	ntation brass cap replacing 1/4" r	erod & monument	San Charles	The state of the s
S 52 W 52.79' PK/remon tag north	west side power pole		A JOSE	PH C. A A A A A A A A A A A A A A A A A A
S 04 W 51.47' PK/remon tag west side power pole			PROFES	SIONAL B
N 40 E 71.06' PK/remon tag north N 15 W 79.98' PK/remon tag north			91 () 1	EYOR TOTAL
			Y 44 47. DL	# <b>**</b> 3 <b>*</b>

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197

POFESSION