UBER 17932 PC 770

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in						
	Located In: Farmin	gton Twp. Comer C	ode #			0.038
1. Public Land Survey	T <u>1-N</u> R <u>9-E</u> T R	C-1:	1			102
	TR TR	SURVEY	&	,	Compliance with ACT 345, P.A. 19	
Z. Hoperty Controlling 3 1 1 1 1 Ki Iko i Zbo of						UMENTATION
Property in Sec. S	ty in Sec. S T R MAR 2 1 2000			2 JAN 98	9:02 A.H.	np & File Number RECEIPT# 12A
4. Lot No, Recorded	Plat	SECTION	V	PAID LYNN D. A	LLEN, CLERK/REG	OAKLAND COUNTY ISTER OF DEEDS
5. Private Claims	P-12			2 6 3	-5-4-	3 - 2 - 1 -
L. Latino N. Charles Inc. 18 and 18		40.07		4 7	8 9	10 11 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey						
decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of						-222324
Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded				10 30	29 26	27-26-25-
on this certificate.				11 12 31	32 33	34 35 36
			•	13		
A. Description of original monumer 1817 Set post corner	nt and accessories	and/or subsequent a	restoration: n/a	GLO notes		
1971 Not described 1972 1/2" Diameter iron bar 1977 Not described 1978 Found iron	÷	O. Boss T. Wozniak T. Parish T. Parish	#13574 #15066 #24609 #24609	Survey L5781, L.C.R.C. L7000 Survey L7141, L.C.R.C. L7353), P840 P125 B, P26, 27	
1991 Found iron in well		T. Wozniak	#15066	L.C.R.C. L1218	67, P620	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A 1/2" iron in monument box currently occupies this corner. Current measurements match one tie from L.C.R.C. L7000, P840 and four ties from L.C.R.C. L12157, P620. Field measurements were made between the following corners:						
C-10 to C-11 2652.80 meas. 2640.00 Rec. G.L.O. 2652.82 Rec. Plats L159, P28-31 2653.98 Tax maps		.L.O. ats L159, P28-31 x maps	C-11 to C- 2651.54 2640.00 2652.47 2651.00	meas. Rec. G.L.O.	0-11	-11 meas. Rec. G.L.O. Rec. Survey L7141, P125
C. Description of monument for	corner and access	ories established to	perpetuate	locating the position	on of the corner:	,
S. 45° W., 81.00' P.K. nail and S. 45° E., 78.22' P.K. nail and N. 45° E., 60.91' P.K. nail and S. 40° W., 84.87' Found concre	eter gate valve remon. washer in E. remon. washer in W. remon. washer in N. ote monument	face U-Pole . face U-pole face U-pole		STATE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TO THE PERSON NAMED IN	OF MICHIGAN JOHN N. REDASH OFESSIONAL	box. Witness ties
No. 37281 The selected location is accepted by me and generally accepted by Professional Surveyors as the lest available endead of the position of the original corner.						
Signed bySurveyor's Michigan License No	37281	eh-		Date	April 24, 199	7
	-				or morreenable c	IENTEVODE IAM 90 107