DEC | 896305730

MAY 2 2 1997 COMMISSION

LAND CORNER RECORDATION CERTIFICATE 7.00 HISCELLANEOUS RECORDING

For corners in		Filing Requirement of Act 74, Mich. P.A. 19	# 4.VV 1	REHONUMENTATION 6 1:39 P.M.	RECEIPT# 35B	
	Oakland (County)	Located in: Farmington Corner Code # Township	PAID		DAKLAND COUNTY	
1. P	ublic Land Survey	T 1N R 9E M-7 T R T R		ACT 345, P.A. 1	1930	
		TR	OAKLANI	D ON: 10 - 25 - 10 COUNTY REMO	NUMENTATION	
***		TR		EER GROUP COM of Deeds Stamp &		
•		TR		*******	S. 10	
4 1:	ot No Reco	orded Plat				
			A	BCDEFO	3 H J K L	
			2 -	6 - 6 - 4 -	3-1-2-1-	
I. Randy Kolehouse , in a field survey on September 2 19 96 , do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the						
Manac	current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a solution of Law; established, re-established, monumented, re-monumented, recovered, found as						
	ssed below:		10	30 29 28	272625	
NOTE	on this certificate.	ers, all in the same town and range, may be recorded	11			
A.	Description of original me	onument and accessories and/or subsequent restoration:	12	31 32 33	35 36	
M-7	1817 Wampler 1939 Baldwin 1987 Gorman	G.L.O. Set Pos County Surveyor's Notes Book 35-43 Iron Pig	t (T1N, R10E			
В.	·	idence found and/or method applied in restoring or reesta			d 11 Mile Road	
M-7	-7 Found a 1-1/2" iron bar in a monument box at the C/L intersection of Inkster Road running North and South and 11 Mile Road running East and West per L.C.R.C. L. 10295 P. 551. This corner checks closely the distance South to M-8 per Baldwin's survey of 1939 and West to L-7 per the Lincolnshire and Churchill Estate Subdivisions.					
	L.C.R.C. L. 10295 P. 551 N 60° E 73.45' Nail & MD S 35° E 73.28' Nail & MD S 65° W 91.10' Chiseled ' N 35° W 66.80' Chiseled '	OT Cap in Lt. Pole OT Cap in Lt. Pole "X" Rim of Manhole				
Measure South 2641.60' to M-8 (G.L.O. = 2640.0') (Churchill Est. = 2641.69') (Calc Baldwin 1939 = 2643.3') Measure West 2638.82' to L-7 (G.L.O. = 2625.48') (Baldwin 1939 - 2631.2') (Churchill Est. & Lincolnshire Sub. = 2639.6 \pm ')						
C.	Description of monumen	nt for corner and accessories established to perpetuate lo	cating the po	osition of the co	rner:	
M-7	Replaced the 1-1/2" iron be existing monument box.	bar with a 5/8" x 24" rebar with brass cap stamped "Oakland	County Rem	onumentation P.S	S. #25854" in an	
	Set PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in NW Side P. Pole N 56° E 73.46' Set PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in NE Side P. Pole S 34° E 73.31' Set PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in SE Side P. Pole S 56° W 82.12' SE Cor. Conc. Pad to Lift Station Riser N 42° W 80.66' RANDY J.					
	The selected location is a surveyors as the best available.	accepted by the Contractor and is generally accepted by profailable evidence of the position of the original corner.	essional	*	KOLEHOUSE LAND SURVEYOR No.	
Signed by Alling French Date Date Date 25854						
Surveyor's Michigan License No. 25854 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963						