. LIBER 16848 1793

DEC | 8 96 3 0 5 7 3 3

MAY 2-2 1997; COMMISSION

\$ 7.00 HISCELLANEOUS RECORDING
LAND CORNER RECORDATION CERTIFICATE\$ 2.00 REHONUMENTATION

RECEIPTION RECORDATION RECEIPTION RECEIPTI

		Filing Requirement of Act 74, Mich. P.A. 197	70 18 DEC 96 1:44 PAID RI	CORDED - OAKLAND COUNTY
For co	orners in			CLERK/REGISTER OF DEEDS
	Oakland (County)	Located in: Farmington Corner Code # Township	4,1334	
	ublic Land Survey	T 1N R 9E M-10 T R T R T R	ACT 3 APPROVED ON: 10	pliance with 145, P.A. 1990 0-26-96 73 Y REMONUMENTATION
	roperty Controlling	STR		T REMONUMENTATION OUP COMMITTEE
	Section liscellaneous	STR	Register of Deed	s Stamp & File Number
	roperty in Sec.	STR		
				•
		Recorded Plat	A B C () E F G H I J K I
J. F	rivate Cialitis		2 .	
			3 5	
1 1	Dandy Kolohovoo	in a field authory on Contember 2 19 06		9 9 10 11 1
do her	eby certify that under re	, in a field survey on <u>September 2</u> 19 <u>96</u> equirements of P.A. 74 Michigan P.A. of 1970, the comer points mention	ed 5	
		in conformance with regulations and rules therefore as required in tructions of the United States Department of the interior, Bureau of La		71615141
Manag	gement or by a decree o	f a Court of Law and/or that the comer points mentioned in lines 3, 4 and	15 7	
above	were in conformance w	ith the rules of the Michigan Board of Land Surveyors or by a Decree o	fa a	21 - 22 - 23 - 2
	of Law; established ised below:	, re-established, monumented, re-monumented, recovered, found		
NOTE	: Not more than 4	corners, all in the same town and range, may be recorded		9
	on this certificate	9.	12313	2 33 34 35 35
A.	Description of origin	al monument and accessories and/or subsequent restoration:	13	
M-10	1817 Wample 1978 Cantrell			
	Records indicate thi	s corner is common with A-10, T1N, R10E.		
В.	Description of corne	er evidence found and/or method applied in restoring or reestab	ilishing corner:	
	Found a 5/8" iron pip L.C.R.C. L. 7252 P.	te 5.75' West of the C/L of Inkster Road running North and South 520. Per note on L.C.R.C. L. 7252 P. 519, this corner was also to East-West fence line position.	and 60.18' West o	f concrete monument per DeDecker & Associates in
	L.C.R.C. L. 7252 P. 9 Plat Mon. East 60.10 Twin 8" Hickory NE 4)' (m. 60.18')		
		4.53" to M-9 (G.L.O. = 2640.0') 6.95' to M-11 (G.L.O. = 2640.0')		
C.	Description of monu	rment for corner and accessories established to perpetuate loc	ating the position	of the corner;
M-10	Replaced the 5/8" iro set a monument box	on pipe with a 5/8" x 24" rebar with brass cap stamped "Oakland Co	ounty Remonumen	tation P.S. #25854." Also
	Set PK Nail & Tag St Set PK Nail & Tag St	tamped "Oakland Co. Remonumentation P.S. #25854" in NE Side tamped "Oakland Co. Remonumentation P.S. #25854" in NW Side tamped "Oakland Co. Remonumentation P.S. #25854" in SW Side tamped "Oakland Co. Remonumentation P.S. #25854" in SE Side	Twin 10" Hickory N 10" Pine S 32° E 6	1 54° E 45.80'
	5/8" Pipe in Conc. M			STATE OF MICA
		n is accepted by the Contractor and is generally accepted by profest tavailable evidence of the position of the original corner.	ssional	RANDY J. KOLEHOUSE LAND SURVEYOR
Signe	d by Kan	dy & Krolebruse Date 12	110/90	No. 25854
Surve	yor's Michigan Licens	EARTH TECH e No		LAND SURVE