LIBER 15288 PC 519 MAY - 1 1005

Mar 1095040433

OK - T SMITH

	MB1 T 1995	į								~ · · · ·							
For	COMMISSION or corners in Oakland		Filing Requirement of Act 74, Mich. P. Commerce Twp. Located In: Corner Code ##					\$ 7.00 MISC RECORDING CHG - IN HOUSE P.A. 1970 MAR 95 4:03 P.M. RECEIPT# 1778 PAID RECORDED - DAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS									
	(County)		Locate	u III.		Corner C	ode =##	L	TIMM D	- ALL	EN: L	LENK!	NEU.	DIEN	ur .	T.E.E.Tr.2	ŧ
1.	Public Land Survey			i R . R .		A-3		Compliance with ACT 345, P.A. 1990									
_			T T	R. R.				API OAI	PROVE KLANI	ED ON D COL	ÇI YTNU	-27 REM	-9'	H MENI	TATI	ON	
2.	Property Controlling		T						P.	EER (ROU	P CO!	MMI	TEE			
	in Section																
3.	Miscellaneous	S	T	R.				Re	giste	r of D)eeds	Star	no &	File	Nun	her	
	Property in Sec.	S	T	R .													
4.	Lot No.	, Recorded	Plat						_ ,		c 0	Ε		н		.,	
	Private Claims								- ₂ [Ţ	ĬĬ	1		Ť	ΪŢ	Ť	T
									3	-6-			îΤ	_3_		土	ì
	David Pawlaczy	⁄k			Dece	ember 1		94	4	_ }_	8-	1	9 —	-10		,	-12
٠ _									5	-	1	 _	.		\sqcup		\perp
ot	hereby certify that under	requirements	of P.A. 7	4. Mich	igan P.A.	of 1970, the corr	er points ment	ioned		1		- 1	i I	- 1	1	ŀ	-1

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

1979 P.K. nail in

expressed below:

pavement

L.C.R.C. J. Smith

#21582

L7593 P302

12

1/2" Iron in 1990

monument box L.C.R.C. B. Thompson

#23828

L12060 P458

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 1/2" iron rod in an existing monument box in asphalt pavement currently occupies this corner. The following witness ties were used to recover and verify its position:

2 ties match L.C.R.C. L12060 P58

1 tie matches L.C.R.C. L7593 P302

		ade betwee	en the following cor	ners:
A-3 to A-2 2620.95		meas.		
	2624.47	rec.	Property desc.	Oakland County Planning
A-3 to B-3	2890.80	meas.	*	
	2875.62	rec.	G.L.O.	Notes
	2891.20	rec.	Survey	L9887 P439
A-3 to A-4	2641.39	meas.		
	2640.90	rec.	Property desc.	Oakland County Planning
A-3 to M-3	126.15	meas.		
	126.33	rec.	L.C.R.C.	L12060 P458
	114.84	rec.	G.L.O.	Notes
Description of I	monument for	corner and	accessories establi	ished to perpetuate locating ti

the position of the corner:

1.00 200

MICH

DAVID

PAWLACZYK

LAND

SURVEYOR NO.

1763

I placed a 2" diameter brass cap stamped "Oakland County Remonumentation PS #17632" on the existing 1/2" iron rod in an existing monument box in asphalt pavement.

N.55° E. 73.76' S.19° W. 88.27' N.29° W.

P.K. nail and O.C.R. tag center asphalt rip-rap

P.K. nail and O.C.R. tag in E. face D.E. pole

52.031 126.15' Due North

P.K. nail and O.C.R. tag in N.E. face utility pole 1/2" Iron rod S.E. corner section 1, T-2-N., R-7-E.

The selected location is accepted by me and generally accepted by Professional Surveyors as the best available. exidence of the position of the original corner.

Signed by Surveyor's Michigan License No. ___17632 Date 2-16-95