MAY - 1 1995

LIBER 15288 pc 497

\$ 7.00 MISC RECORDING CHG - IN HOUSE

\$ 2.00 RENON CHG - IN HOUSE

	LAND CORNER RECORDATION CEI	R
:OMMISSION	ST 2	

ITIFICATE HAR 95 4:00 P.M. RECEIPTR 1778

Con comment in	Oakland	Fili	ng Require Commerc	ment of Act 74, Mi e Twp.		D N D. ALLI		XED - O XK/REGI				
1. Public Land St	ırvey	T	R <u>8E</u> R	Corner Code ## K-10	— APPROV		pliance v 345, P.A. /2- 0.5	vith 1990 ;_ 94		FION		
2. Property Control in Section 3. Miscellaneous Property in Se	s s	T	R		— Regi	PEER GR	OUP COM	MMITTE	EE.			
						A 8	CDE	FG	н	ı J	K L	L M
in lines 1 and 2 about current manual of su Management or by a above were in confo Court of Law; esta expressed below: NOTE: Not more on this co	tunder requirement ove were in conform prey instructions of decree of a Court of rmance with the rule blished, re-establis than 4 corners, a ertificate.	s of P.A. 74, ance with re the United Law and/or as of the Mic shed, monu	n	ber 25 of 1970, the corner point of rules therefore as required to the Interior, Bur points mentioned in ling Land Surveyors or by a conumented, recovered the range, may be recovered for subsequent restors.	s mentioned puired in the reau of Landes 3, 4 and 5 a Decree of a d, found as	2 6 3 4 7 5 6 18 7 8 19 9 10 30 11 12 31 13	3-17-20-29-32	21 28 33 33	-10 -15 -22 -27 -34	-1114		13-24-36-36-36-36-36-36-36-36-36-36-36-36-36-
	Post 1/2" Iron in	G.L.O.	A. Holmes	N/A	Notes							
	monument box	L.C.R.C.	D. Finney	#15536	L8758 P611							
1909	monument box	L.C.R.C.	K. Schultz	#31610	L10966 P42	1						

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 1/2" iron rod in a monument box in asphalt pavement currently marks this corner. The following witness ties were used to recover and verify its position:

1 tie from L.C.R.C.

L8758 P611

5 ties from L.C.R.C.

L10966 P421

31
_
Smith #33140)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I placed a 2" diameter brass cap stamped "Oakland County Remonumentation PS #176	32" on an existing
1/2" iron re-rod in the existing monument box in asphalt pavement.	
N.71° W. 83.71′ P.K. nail and O.C.R. tag in N.E. face M.B.T. pole	

N.50° E. 37.08' S.39° E.

P.K. nail and O.C.R. tag in N.W. face M.B.T. pole

100.124

P.K. nail and O.C.R. tag in N.E. face 48" Willow

S.45° W. 81.56' P.K. nail and O.C.R. tag in S.E. face D.E. pole

The selected location is accepted by me and generally accepted by Professional Surveyors as the best ava evidence of the position of the original corner.

Surveyor's Michigan License No.

2-16-95 _ Date

> FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

DAVID

PAWLACZYK

LAND SURVEYOR NO.

17632