# SURVEY & REMONUMENTATION

MAR 0 4 1998

### UMR 17156M250

**SECTION** 

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		
Oakland	Located In: Troy Twp. Corner Code #	\$ 9.00 MISCELLANEOUS RECORDING
(County)		\$ 2.00 REMONMENTATION
1. Public Land Survey	T 2NR 11EL-11	24 APR 97 8:45 A.M. RECEIPT# 34A PAID RECORDED - CAMLANG COUNTY
•	<u>TR</u>	LYNN D. ALLEN, CLERK/REGISTER OF DEEGS
	T R	وردستان المامان المامان
2. Property Controlling	s TR	ACT 345, P.A. 1009 4714 57 TS
in Section	s	APPROVED ON: 4-16-57 TS OAKLAND COUNTY REMONENCY LINE
3. Miscellaneous	S TR	PEER GRO'S ASSESSMENT
Property in Sec.	5 1 K	Register of Deeds Stamp & File Number
	rded Plat	A B C D E F G H I J K L M
5. Private Claims		2 6 5 4 3 2
		3
: Unatar P Pannadir	, in a field survey on3/17_, 1997 do hereby state that under	
requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in		
conformance with regulations and	drules therefore as required in the current manual of survey instructions of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	6 19 17 16 15 14 13
that the corner points mentioned	I in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	
Board of Land Surveyors or by recovered, found as expressed be	y a Decree of a Court of Law; established, re-established, monumented,	8 19 20 21 22 23 24
•		9
NOTE: Not more than 2 con on this certificate.	ners, all in the same town and range, may be recorded	10 30 29 28 27 26 25
On this certificate.		11
		12 31 32 33 34 35 36
		13
<i>3.1</i> , 1550 11461, 10 poor	21; LCRC L.16037, Pg.649 - Fnd 1/2" Iron Rod in a Monument Bo	
1997 Kennedy Surveying, extending to the Ed North. There is a	idence found and/or method applied in restoring or reestablishing or Inc Kennedy, PS #17623 - Fnd 1/2" Iron in a Monument Box in ast & West, which has a concrete surface, also 16 feet East of fence/tree line extending to the North.	the center of the left turn lane for Maple Road the center of a driveway for house \$2475 to the
	C #1, 2, 3 were used to recover and verify the location of t	
I accepted the fou	nd 1/2" Iron in a Monument Box as the best evidence of the o	riginal corner position.
		$\sim$ $\langle I_{L_{n}}$
Field measurements	between see back side of LCRC	9231
C. Description of monumen	nt for corner and accessories established to perpetuate locating the	position of the corner:
L-11 I replaced the fou	und 1/2" Iron Rod with a 5/8" x 24" Iron Rod w/2" diameter busting Monument Box	
NO6°E 53.59' Set P N51°W 150.36' Set	PK & Remon Washer West face Power Pole PK & Remon Washer SW face Power Pole PK & Remon Washer SW face 13" Ash	Mulliture.
S68°W 200.05' Set	PK & Remon Washer NW face Guide Pole	MARKE OF MICHOLINE
The selected location is position of the original	is accepted by me and is generally accepted by Professional al corner.	Surveyors as the est available evidence the HUSTON KENNEDY PROFESSIONAL SURVEYOR 17023
Signed by	1	7-17-97 FA PHOFESSIONAL A SURVEYOR 17023
Surveyor's Michigan License	e No	TO ESSIONA SURPLEMENTAL
		in the state of th

## SURVEY & REMONUMENTATION

MAR 04 1998

UBER 17156 M 251

SECTION

#### FIELD MEASUREMENTS BETWEEN

#### <u>L-11 to K-11</u>

GLO = 39.70 chains or 2620.20 Ft.
"SUPERVISOR'S PLAT OF MAPLE ACRES" = 2643.58 Ft.
"GULASON SUBDIVISION" + Parcels + "FAIRGROVE SUBDIVISION" = 2644.34 Ft.
GPS-MEA = 2644.16 Ft.

### <u>L-11 to M-11</u>

GLO = 39.70 chains or 2620.20 Ft.
M.C.S. = 2615.23 Ft. (No date stated)
"SUPERVISOR'S PLAT OF PLAINVIEW FARMS" = 2615.73 Ft.
"CARLSTON HEIGHTS SUBDIVISION" + Parcels = 2617.05 Ft.
GPS-MEA = 2615.27 Ft.