MAY 24 2000

LIBER 20560 - 193

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

•	Filing Requirement of Act 74, Mich. P.A.	1970
For corners in		345418
Oakland (County)	Located In: Corner Code # Highland Township	LIBER 20560 PAGE 493 \$9.00 HISC RECORDING \$2.00 REMONUMENTATION
1. Public Land Survey	T3N R7E C-6 T R T R	09/20/1999 08:42:57 A.M. RECEIPT# 7977 PAID RECORDED - DAKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER OF D
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S	Compliance with ACT 345, P.A. 1990 APPROVED ON: 8-71-95 JL OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		
I. Huston K. Kennedy requirements of P.A. 74, Michigan conformance with regulations and runited States Department of the Introduction of the Intro	In a field survey on April 15 1999 do hereby state that under P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in ules therefore as required in the current manual of survey instructions of the erior, Bureau of Land Management or by a decree of a Court of Law and/or lines 3, 4 and 5 shove were in conformance with the rules of the Michigan a Decree of a Court of Law; established, re-established, monumented.	6 -18 -17 - 16 - 15 - 14 - 13
NOTE: Not more than 2 corn	ers, all in the same town and range, may be recorded	9
on this certificate.		10 30 29 28 27 26 25 11 1 2 32 33 34 35 36
 1.) 1990-Bonno, PS #32332; LCRC L.11603, Pg. 674 – Fnd a ½" Re-rod & Monument Box 2.) 1989-Bonno, PS #32332; Survey L.11603, Pgs. 685 & 686 – Fnd a ½" Re-rod & Monument Box, same wit as 1990 LCR 3.) 1962-Oakland County Road Commission unrecorded witnesses – Fnd a 1" Pipe 4.) 1928-Baldwin, PS #1298; Unrecorded Survey – Fnd a Iron Pipe over stone & bricks (Con't on back side) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1999-Kennedy Surveying, Inc. – Kennedy, PS #17623 – Fnd a ½" Iron Rod in a Monument Box located 2 feet West of the existing centerline of Hickory Ridge Road extending to the North & South, which has a bituminous surface. A tree-fence of extending to the East & West. Witnesses from #1, 3 & 4 were used to recover and verify the location of the found ½" Iron Rod in a Monument Box. I accepted the found ½" Iron Rod in a Monument Box as the best evidence of the original corner positon. 		
FIELD MEASURMENTS BETWEEN		
C-6 to C-5 GLO = 40 chains or 264 Sidwell W ½ Sec 17 (11- Sidwell E ½ of NE ½ Sec 2655.26 Ft. LCRC recor "HICKORY RIDGE EST Unrecorded Survey by I Unrecorded Survey by I	0.00 Ft. -17) = 2655.59 Ft. c 18 (11-18D) = 2654.60 Ft. rded in Liber 11603, page 674 ATES NO. 1" + Parcels (Sec 18) = 2654.60 Ft. Raymond Kostecke, PS #12584, dated 11/20/87 = 2654.60 Ft. Raymond Kostecke, PS #12584, dated 7/19/87 = 2654.58 Ft. Raymond Kostecke, PS #12584, dated 11/4/68 = 2654.60 Ft.	HUSTON KENNEDY PROFESSIONAL SURVEYOR 17623
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-6 I replaced the found ½" Iron Rod with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland County Remonumentation, PS #17623 in an existing Monument Box Due West 59.49' Set Mag Nail & Remon Washer South face Power pole S44°E 151.29' NW corner of house #2260 Due East 84.26' Set Mag Nail & Remon Washer North face Power Pole S49°W 46.11' Set Mag Nail & Remon Washer SE face 11" Box Elder		
The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence the position of the original corner.		
Signed by:	Date	9-1-99
Surveyor's Michigan License	1 1 / /	