MAY 2 4 2000

SECTION

## 10002032916644

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Oakland	Located In: Corner Code #	,
(County)	Highland Township	273078
1. Public Land Survey	·	LIBER 20329 PAGE 644
Conc Carlo Sulvey	<u>T3N R7E D-3</u>	i +7.00 alsc recording
	T R R	\$2.00 REMONIMENTATION 07/29/1999 11:46:22 A.M. RECEIPT# 58
,	R.	PAID RECORDED - DAKLAND COUNTY  6. WILLIAM CADDELL, CLERK/REGISTER OF
2. Property Controlling	S T B	Compliance with
in Section	STR	ACT 345, P.A. 1990
3. Miscellaneous	S T_ R	APPROVED ON 6-6-55 50
Property in Sec.	S T R S T R S T R	GARLAND COUNTY DEMONSTRATION
4. Lot No Bassa		PEER GROUP COMMITTEE  Register of Deeds Stamp & File Nur
5. Private Claims	rded Plat	-
,		1 B C D E F G H I J K L
	•	2 - 6 5 3 3 1
Huston K. Kennerty :	in a fuld St	3
equirements of P.A. 74, Michigan	in a field survey on March 1 , 1999 do hereby state that under P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in the current manual of express the state of the current manual of express the corner in the current manual of express to the current manual of express the current manual of express to the current manual of express the current manua	
Inited States Commissions and ru	hes therefore as required in the current manual of a way 2 above were in	
nat the corner points mentioned in it	Alea therefore as required in the current manual of survey instructions of the erior, Bureau of Land Management or by a decree of a Court of Law and/or ines 3, 4 and 5 above were in conformance with the rules of the Michigan Decree of a Court of Law, established, regardablished.	6 18 17 16
covered, found as empressed button	thes 3, 4 and 5 above were in conformance with the rules of the Michigan of a Court of Law; established, re-established, monumented, w:	7
- tu apper neith	. However, more than early	;
OTE: Not more than 7 and	m all la d	8 20 21 22 23 24
on this certificate.	rs, all in the same town and range, may be recorded	9
	•	10 30 29 28 27 26 25
		11
		12 31 32 33 34
1.) 1974-Feldhauser, Pt	nument and accessories and/or subsequent restoration: S.; Set Post 10" White Oak N29°E 51 Links; 10" White C S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd 2.1" Pine	12 31 32 33 34 35 36 Dak S80°E 93 Links
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2 5.) 1987-Thompson, Do	S #10685; LCRC L.6409, Pg.474 — Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 — Fnd a 1" Pipe 2005; Unrecorded Survey — Object found not stated, no w 1270; Unrecorded Survey — Fnd ½" Iron	12 31 32 33 34 35 36 Dak S80°E 93 Links
<ol> <li>1.) 1974-Feldhauser, Pt</li> <li>2.) 1993-Bonno, PS #32</li> <li>3.) 1978-Ross, PS #190</li> <li>4.) 1974-McCoy, PS #2</li> <li>5.) 1987-Thompson, PS</li> <li>6.) 1989-Bonno, PS #32</li> </ol>	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd a ¾" Pipe 2332; Unrecorded Survey – Fnd ½" Pipe, used same wit	12 -31 - 32 - 33 - 34 - 35 - 36 - 36 - 36 - 36 - 36 - 36 - 36
<ol> <li>1.) 1974-Feldhauser, Pt</li> <li>2.) 1993-Bonno, PS #32</li> <li>3.) 1978-Ross, PS #190</li> <li>4.) 1974-McCoy, PS #2</li> <li>5.) 1987-Thompson, PS</li> <li>6.) 1989-Bonno, PS #32</li> </ol>	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd a ¾" Pipe 2332; Unrecorded Survey – Fnd ½" Pipe, used same wit	12 31 32 33 34 35 36 Dak S80°E 93 Links itnesses
<ol> <li>1.) 1974-Feldhauser, Pt</li> <li>2.) 1993-Bonno, PS #32</li> <li>3.) 1978-Ross, PS #190</li> <li>4.) 1974-McCoy, PS #2</li> <li>5.) 1987-Thompson, PS</li> <li>6.) 1989-Bonno, PS #32</li> <li>Description of corner evident</li> <li>1999-Kennerty Surveying</li> </ol>	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 2332; Unrecorded Survey – Fnd ½" Iron 2332; Unrecorded Survey – Fnd ½" Pipe 2332; Unrecorded Survey – Fnd ½" Pipe, used same with the found and/or method applied in restoring or reestablishing	Dak S80°E 93 Links itnesses as 1993 LCRC (Con't on back side of LCRC)
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner eviden 1999-Kennedy Surveying Road extending to the East	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Iron 2332; Unrecorded Survey – Fnd ½" Pipe 2332; Unrecorded Survey – Fnd ½" Pipe, used same with not found and/or method applied in restoring or reestablishing 1, Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8. West, which has a gravel surface. Old fence-tree row extens	Dak S80°E 93 Links  itnesses  as 1993 LCRC  (Con't on back side of LCRC)  ed 6 feet South of the existing centerline of Clystage of the treatment of treatment of the treatment of the treatment of the treatment of treatment of the treatment of the treatment of the treatment of t
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Iron 2332; Unrecorded Survey – Fnd ½" Pipe used same with not found and/or method applied in restoring or reestablishing g. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate & West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the found in the surface of the surface.	Dak S80°E 93 Links  itnesses  as 1993 LCRC (Con't on back side of LCRC) corner: ed 6 feet South of the existing centerline of Clyring to the North & South.
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 I accepted the found 1" In	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd a ¾" Pipe 2332; Unrecorded Survey – Fnd ½" Pipe, used same wit not found and/or method applied in restoring or reestablishing g, Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate & West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the Iron Pipe as the best evidence of the original corner position.	Dak S80°E 93 Links  itnesses  as 1993 LCRC (Con't on back side of LCRC) corner: ed 6 feet South of the existing centerline of Clyring to the North & South.
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 I accepted the found 1" in	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 2005; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 8 #23828; Unrecorded Survey – Fnd ½" Iron 2332; Unrecorded Survey – Fnd ½" Pipe, used same with the found and/or method applied in restoring or reestablishing 1. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8. West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the fron Pipe as the best evidence of the original corner positions as the side of LCRC.	Dak S80°E 93 Links  itnesses  as 1993 LCRC (Con't on back side of LCRC) corner: ed 6 feet South of the existing centerline of Clyring to the North & South.
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 I accepted the found 1" in Field measurements see ba	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 8 #23828; Unrecorded Survey – Fnd ½" Iron 8 #23828; Unrecorded Survey – Fnd ½" Pipe, used same with note found and/or method applied in restoring or reestablishing 13. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8. West, which has a gravel surface. Old fence-tree row extend 8. West, which has a gravel surface of the original corner position of Pipe as the best evidence of the original corner positics side of LCRC	Dak S80°E 93 Links  itnesses  as 1993 LCRC (Con't on back side of LCRC) corner: ed 6 feet South of the existing centerline of Clyring to the North & South.
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 I accepted the found 1" in Field measurements see ba	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 8 #23828; Unrecorded Survey – Fnd ½" Iron 8 #23828; Unrecorded Survey – Fnd ½" Pipe, used same with note found and/or method applied in restoring or reestablishing 13. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8. West, which has a gravel surface. Old fence-tree row extend 8. West, which has a gravel surface of the original corner position of Pipe as the best evidence of the original corner positics side of LCRC	Dak S80°E 93 Links  itnesses  as 1993 LCRC (Con't on back side of LCRC) corner: ed 6 feet South of the existing centerline of Clyring to the North & South.
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of comer eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 I accepted the found 1" in Field measurements see ba Description of monument for D-3 I replaced the found 1 Remonumentation, PS #1	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Iron 2332; Unrecorded Survey – Fnd ½" Pipe, used same with nee found and/or method applied in restoring or reestablishing g. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate & West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the 1 Iron Pipe as the best evidence of the original corner positions are side of LCRC.  corner and accessories established to perpetuate locating the "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter brase "Iron Rod w/2" diameter	Dak S80°E 93 Links  itnesses  as 1993 LCRC (Con't on back side of LCRC) corner: ed 6 feet South of the existing centerline of Clyring to the North & South.
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of comer eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 I accepted the found 1" in Field measurements see ba Description of monument for D-3 I replaced the found 1 Remonumentation, PS #1 N72°E 92.15' Set Mag No.	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3" Pipe 2332; Unrecorded Survey – Fnd ½" Iron 3" Pipe 2332; Unrecorded Survey – Fnd ½" Pipe, used same with nee found and/or method applied in restoring or reestablishing It. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8. West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the 1 Iron Pipe as the best evidence of the original corner positions and accessories established to perpetuate locating the 1" Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter bras 1" Iron Pipe with a 5/8" x 24" Iron	Dak S80°E 93 Links  itnesses  as 1993 LCRC  (Con't on back side of LCRC)  ed 6 feet South of the existing centerline of Clyring to the North & South.  ocation of the found 1° Iron Pipe.  on.  position of the compensation of Michigan Scap staroped Oakland Gound  s cap staroped Oakland Gound
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 Laccepted the found 1" in Field measurements see ba Description of monument for D-3 I replaced the found 1 Remonumentation, PS #1 N72°E 92.15' Set Mag Nai N49°W 49.96' Set Man Nai	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Iron 2332; Unrecorded Survey – Fnd ½" Pipe, used same wit not found and/or method applied in restoring or reestablishing g. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8 West, which has a gravel surface. Old fence-tree row extend 8. West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the 1 fron Pipe as the best evidence of the original corner positions ack side of LCRC corner and accessories established to perpetuate locating the "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter bras 1 & Remon Washer SE face 19" Oak	Dak S80°E 93 Links  itnesses  as 1993 LCRC  (Con't on back side of LCRC)  ed 6 feet South of the existing centerline of Clyring to the North & South.  ocation of the found 1° Iron Pipe.  on.  position of the compensation of Michigan Scap staroped Oakland Gound  s cap staroped Oakland Gound
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 Laccepted the found 1" in Field measurements see ba Description of monument for D-3 I replaced the found 1 Remonumentation, PS #1 N72°E 92.15' Set Mag Nai N49°W 49.96' Set Mag Nai N49°W 49.96' Set Mag Nai S70°W 71.35' Set Mag Nai	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Pipe 2332; Unrecorded Survey – Fnd ½" Pipe, used same wit noe found and/or method applied in restoring or reestablishing g. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8. West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the fron Pipe as the best evidence of the original corner position of Pipe with a 5/8" x 24" Iron Rod w/2" diameter bras 7623.  If & Remon Washer SE face 19" Oak ill & Remon Washer NE face 8" Oak	Dak S80°E 93 Links  itnesses  as 1993 LCRC  (Con't on back side of LCRC)  ed 6 feet South of the existing centerline of Clyring to the North & South.  ocation of the found 1° Iron Pipe.  on.  position of the compensation of Michigan Scap staroped Oakland Gound  s cap staroped Oakland Gound
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32  Description of corner eviden 1999-Kennedy Surveying Road extending to the East  Witnesses from LCRC #1  I accepted the found 1" in  Field measurements see ba  Description of monument for D-3 I replaced the found 1" Remonumentation, PS #1: N72°E 92.15' Set Mag Nai N49°W 49.96' Set Mag Nai N49°W 49.96' Set Mag Nai S70°W 71.35' Set Mag Nai S18°W 31.76' Set Mag Nai	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Pipe, used same wit noe found and/or method applied in restoring or reestablishing g. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8 West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the 1 fon Pipe as the best evidence of the original corner position of the pipe with a 5/8" x 24" Iron Rod w/2" diameter bras 7623  If & Remon Washer SE face 19" Oak il & Remon Washer NW face 32" Twin Oak il & Remon Washer NW face 32" Twin Oak il & Remon Washer NW face 11" Oak	Dak S80°E 93 Links  itnesses  as 1993 LCRC  (Con't on back side of LCRC)  ed 6 feet South of the existing centerline of Clyring to the North & South.  cocation of the found 1" Iron Pipe.  con.  position of the company of Michigan South  CURVEYOR  17023
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32  Description of corner eviden 1999-Kennedy Surveying Road extending to the East  Witnesses from LCRC #1  I accepted the found 1" in  Field measurements see ba  Description of monument for D-3 I replaced the found 1" Remonumentation, PS #1: N72°E 92.15' Set Mag Nai N49°W 49.96' Set Mag Nai N49°W 49.96' Set Mag Nai S70°W 71.35' Set Mag Nai S18°W 31.76' Set Mag Nai	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Pipe, used same wit noe found and/or method applied in restoring or reestablishing g. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8 West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the 1 fon Pipe as the best evidence of the original corner position of the pipe with a 5/8" x 24" Iron Rod w/2" diameter bras 7623  If & Remon Washer SE face 19" Oak il & Remon Washer NW face 32" Twin Oak il & Remon Washer NW face 32" Twin Oak il & Remon Washer NW face 11" Oak	Dak S80°E 93 Links  itnesses  as 1993 LCRC  (Con't on back side of LCRC)  ed 6 feet South of the existing centerline of Clyring to the North & South.  cocation of the found 1" Iron Pipe.  con.  position of the company of Michigan South  CURVEYOR  17023
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner eviden 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 I accepted the found 1" in Field measurements see ba Description of monument for D-3 I replaced the found 1 Remonumentation, PS #1 N72°E 92.15' Set Mag Nai N49°W 49.96' Set Mag Nai S70°W 71.35' Set Mag Nai S16°W 31.76' Set Mag Nai	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Pipe, used same wit noe found and/or method applied in restoring or reestablishing g. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate 8 West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the 1 fon Pipe as the best evidence of the original corner position of the pipe with a 5/8" x 24" Iron Rod w/2" diameter bras 7623  If & Remon Washer SE face 19" Oak il & Remon Washer NW face 32" Twin Oak il & Remon Washer NW face 32" Twin Oak il & Remon Washer NW face 11" Oak	Dak S80°E 93 Links  itnesses  as 1993 LCRC  (Con't on back side of LCRC)  ed 6 feet South of the existing centerline of Clyring to the North & South.  cocation of the found 1" Iron Pipe.  con.  position of the company of Michigan South  CURVEYOR  17023
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32  Description of corner eviden 1999-Kennedy Surveying Road extending to the East  Witnesses from LCRC #1  I accepted the found 1" in  Field measurements see ba  Description of monument for D-3 I replaced the found 1" Remonumentation, PS #1: N72°E 92.15' Set Mag Nai N49°W 49.96' Set Mag Nai N49°W 49.96' Set Mag Nai S70°W 71.35' Set Mag Nai S18°W 31.76' Set Mag Nai	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 2005; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3 #23828; Unrecorded Survey – Fnd ½" Pipe 2332; Unrecorded Survey – Fnd ½" Pipe, used same wit nee found and/or method applied in restoring or reestablishing g. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate & West, which has a gravel surface. Old fence-tree row extend a west, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the fron Pipe as the best evidence of the original corner position of Pipe as the best evidence of the original corner position of Pipe with a 5/8" x 24" Iron Rod w/2" diameter bras 7623 if & Remon Washer SE face 19" Oak if & Remon Washer NE face 8" Oak if & Remon Washer NW face 32" Twin Oak if & Remon Washer NW face 11" Oak oted by me and is generally accepted by Professional Ser.	Dak S80°E 93 Links  itinesses  as 1993 LCRC  (Con't on back side of LCRC)  corner: ed 6 feet South of the existing centerline of Clyding to the North & South.  ocation of the found 1" tron Pipe.  con.  Position of the corner ENNEDY s cap stemped Oakland County  Surveyors as the best available evidence
1.) 1974-Feldhauser, Pt 2.) 1993-Bonno, PS #32 3.) 1978-Ross, PS #190 4.) 1974-McCoy, PS #2: 5.) 1987-Thompson, PS 6.) 1989-Bonno, PS #32 Description of corner evident 1999-Kennedy Surveying Road extending to the East Witnesses from LCRC #1 I accepted the found 1" in Field measurements see bat Description of monument for D-3 i replaced the found 1" Remonumentation, PS #17 N72°E 92.15" Set Mag Nai N49°W 49.96' Set Mag Nai S70°W 71.35' Set Mag Nai S16°W 31.76' Set Mag Nai selected location is accepted to the original composition of the original composition or the original composition or the original composition or the original composition of the original composition or the original composition o	S #10685; LCRC L.6409, Pg.474 – Fnd ½" Iron Rod 2332; LCRC L.13268, Pg.100 – Fnd a 1" Pipe 205; Unrecorded Survey – Object found not stated, no w 1270; Unrecorded Survey – Fnd ½" Iron 3" Pipe 2332; Unrecorded Survey – Fnd ½" Iron 3" Pipe 2332; Unrecorded Survey – Fnd ½" Pipe, used same with note found and/or method applied in restoring or reestablishing g. Inc. – Kennedy, PS #17623 – Fnd a 1" Iron Pipe locate & West, which has a gravel surface. Old fence-tree row extend 8. West, which has a gravel surface. Old fence-tree row extend 1, 2, Survey #7 & 9 were used to recover and verify the 1 on Pipe as the best evidence of the original corner position of LCRC corner and accessories established to perpetuate locating the "Iron Pipe with a 5/8" x 24" Iron Rod w/2" diameter bras 1 & Remon Washer SE face 19" Oak 1 & Remon Washer NE face 8" Oak 1 & Remon Washer NW face 32" Twin Oak 1 & Remon Washer NW face 32" Twin Oak 1 & Remon Washer NW face 11" Oak 1 Oak 1 of the professional	Dak S80°E 93 Links  itinesses  as 1993 LCRC  (Con't on back side of LCRC)  corner: ed 6 feet South of the existing centerline of Clyding to the North & South.  ocation of the found 1" tron Pipe.  con.  Position of the corner ENNEDY s cap stemped Oakland County  Surveyors as the best available evidence