HBH 20329 MG 48

		LAND CORNER R	ECORDATION CERTIF	273080
For	corners in	Filing Requireme	nt of Act 74, Mich. P.A. 1	976IBER 20329 PAGE 648 \$7.00 MISC RECORDING
_0	akland (County)	Located In: Corner Highland Township	Çode#	\$2.00 REMONUMENTATION 07/29/1999 11:46:39 A.M. RECEIPTH 58917 PAID RECORDED - DAKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS
2, F	Public Land Survey Property Controlling	T3N R7E T R S T R S T R	F-3 RVEV &	Compliance with ACT 345, P.A. 1990
	Miscellaneous Property in Sec.	S_T_R_	Zi 20 00	APPROVED ON: 6-6-79 JK OAKLAND COUNTY REMONUMENTATION
,	roporty in occ.	SE	CTION	PEER GROUP COMMITTEE Register of Deeds Stamp & File Numb
4. Lot No, Recorded Plat				
i, <u>Hi</u> requi confo Unite that the	uston K. Kennedy, rements of P.A. 74, Michigar mance with regulations and d States Department of the inhe corner points mentioned ind of Land Surveyors or by ered, found as expressed beli	In a field survey on March 1, 1999 I. P.A. of 1970, the corner points mentioned in rules therefore as required in the current manuterior, Bureau of Land Management or by a delines 3, 4 and 5 above were in conformance a Decree of a Court of Law; established, low:	n lines 1 and 2 above were in lat of survey instructions of the scree of a Court of Law and/or with the rules of the Michigan re-established, monumented,	1 A B C D E F G H I J K L 2 6 5 4 3 2 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	1823-GLO Wampler, D.S.; Set Post 20" White Oak N26°E 79 Links; 12" White Oak S2 ½°W 82 Links 1.) 1990-Newman, PS #24607; LCRC L.11604, Pg.646 – Fnd ½" Re-rod 2.) 1997-Kapelczak, PS #24598; LCRC L.17129, Pg.704 – Fnd ½" Re-rod 3.) Kapelczak, PS #24598; Unrecorded Survey – Object found not stated, no witnesses 4.) 1983-Bishop, PS #25829; Unrecorded Survey – Object found not stated, no witnesses 5.) 1980-Feldhauser, PS #10685; Unrecorded Survey – Object found not sated, no witnesses 6.) 1943-1948-Oakland County Road Commission Section Ties – Fnd Iron Pin			
•	 Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1999-Kennedy Surveying, Inc. – Kennedy, PS #17623 – Fnd a ½" Iron Rod located in the existing centerline of Clyc extending to the East & West, which has a gravel surface. No lines of occupation. Witnesses from LCPC #1 & 2 Lineareded Witnesses #0 west for the linear point of the linear point o			
	Witnesses from LCRC #1 & 2 Unrecorded Witnesses #6 were used to recover and verify the location of the found ½" Iron Roll accepted the found ½" Iron Roll as the best evidence of the original comer position.			
	FIELD MEASURMENTS		the original corner posit	on.
9	F-3 to E-3 BLO = 40.59 ½ chains or Bidwell E ½ of NW ¼ Sec Sec 9 (11-9A) = 2683.06 2682.37 Ft. (GPS-MEA)	9 (11-9B) + W 1/3 of NW 1/2 of	F-3 to G-3 GLO = 40.59 ½ chains Unrecorded Survey by "HIGHLAND HILLS" + 2687.45 Ft. (GPS-ME)	Joseph Bishop, PS #25829 = 2688.12 Ft. Parcels (Sec. 9) = 2688.77 Ft
R	Description of monument for comer and accessories established to perpetuate locating the position of the comer F-3 I replaced the found ½" Iron Rod with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Caldant Coultry Remonumentation, PS #17623 N45°W 70.77' Set Mag Nail & Remon Washer SW face Power Pole S59°W 63.74' Set Mag Nail & Remon Washer NW face 27" Oak S16°E 31.21' Set Mag Nail & Remon Washer NE face 31" Oak S72°E 91.40' Set Mag Nail & Remon Washer NE face 33" Oak			
The s he p	selected location is acosition of the original of	cepted by me and is generally acc		the state of the s
Signe Super		17173	Date <u>6</u>	-1-99
ourve)	yor's Michignan License	No		