MAY 24 2000

UBER 20934 274

E	~	7	۴	<b>∮</b> →	'nΙ
 7	١.	. 1	ł	1 3	IN.
 to and	•~	Ħ	1	<b>.</b>	

SECTION LAND CORNER RECORDATION CERTIFICATION CERTIFICATIO	
Filing Requirement of Act 74, Mich. P.A. 1 corners in	LIBER 20934 PAGE 274 \$9.00 MISC RECORDING
Akland Located In: Corner Code #  (County) Highland Township	\$2.00 REMONUMENTATION 12/29/1999 02:45:19 P.M. RECEIPT# 110738 PAID RECORDED - NOW OND COUNTY
Jubilic Land Survey         T3N         R7E         1-5           T         R         T         R	G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS
Property Controlling S T R Section S T R Sec	ACT 348, P.A. 1990  APPROVED ON: 11-2-95 Sh  AKLAND COUNTY REMONEMENTATION OF ARREST GROUP COMMITTEE
_ot No, Recorded Plat	Register of Deeds Stamp & File Number
Private Claims	A B C D E F G H I J K L M
luston K. Kennedy , in a field survey on April 15 , 1999 do hereby state that under strements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in formance with regulations and rules therefore as required in the current manual of survey instructions of the ed States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan rd of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, vered, found as expressed below:	3 4 - 7 - 8 - 9 - 10 - 11 - 12 - 5 6 - 10 - 17 - 16 - 15 - 14 - 13 - 7
TE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25
Description of original monument and accessories and/or subsequent restoration: 1823-GLO Wampler, D.S.; Set Post 12" White Oak S14 ½°W 12 Links; 12" White Oak S43°E 80 Links 1.) 1972-Jones, PS #16045; LCRC L.5974, Pg.614 – Fnd a 5/8" Re-rod in a Mc2.) 1962-Oakland County Road Commission unrecorded witnesses – Fnjd a rod.) 1989-Bonno, PS #32332; Unrecorded Survey – Object found not stated, no Description of corner evidence found and/or method applied in restoring or reestablishing 1999-Kennedy Surveying, Inc. – Kennedy, PS #17623 – Fnd a ¾" iron Rod in a Harvey Lake Road extending to the North & South, which has a bituminous surf Lake View Drive extending to the West, which has a gravel surface, also a tree,	d in Wardlow Road witnesses g corner: Monument Box in existing centerline of ace, 30 feet North of the existing centerline of
Witnesses from LCRC #1 were used to recover and verify the location of the for	und ¾" Iron Rod in a Monument Box.
I accepted the found 1/2" Iron Rod in a Monument Box as the best evidence of	the original corner positon.
FIELD MEASURMENTS BETWEEN 1-5 to H-5	AND THE OF MICHAEL AND THE STATE OF MICHAEL AND THE STATE OF MICHAEL AND THE STATE OF THE STATE
No GLO, corner falls in a lake No plat or sidwell distances 2658.84 Ft. (GPS-MEA)  1-5 to 1-6 GLO = 40 chains or 2640.00 Ft. (corner falls in lake)	KENNEDY PROFESSIONAL
"WALING WOODS" (Sec 15) = 2680.44 Ft. Unrecorded Survey by Gilbert G. Bonno, PS #32332 dated 11/1/89 = 2660.26 Ft. 2170.12 Ft. (I-5 to meander corner) 2660.44 Ft. (CAL)	(Con't on back AGESSIONAL SUR
Description of monument for corner and accessories established to perpetuate locating to 1-5 I replaced the found 3/2" Iron Rod with a 5/8" x 24" Iron Rod w/2" diameter brackeronumentation, PS #17623 in a existing Monument Box Due West 61.66' Set Mag Nail & Remon Washer South face Power Pole N32°W 69.32' Set Mag Nail & Remon Washer NE face 10" Maple N86°E 58.22' Set Mag Nail & Remon Washer North face Power Pole S37°E 162.87' Set Mag Nail & Remon Washer SW face Power Pole	he position of the corner:  2p  2ss cap stamped Oakland County  12
e selected location is accepted by me and is generally accepted by Professiona position of the original corner.	al Surveyors as the best available evidence of
ned by: Date	11-11-99