

SURVEY &
REMONUMENTATION

LIBER 15292 PG. 379

MAR 15 95 04 1991

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE

OK - T. SMITH

Filing Requirement of Act 74, Mich. P.A. 1970 7.00 MISC RECORDING CHG - IN HOUSE

For corners in COMMISSION

\$ 2.00 REMON CHG - IN HOUSE
15 MAR 95 8:10 A.M. RECEIPT# 8B
PAID RECORDED - OAKLAND COUNTY
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

OAKLAND
(County)

Located in: WATERFORD Corner Code #

- 1. Public Land Survey T 3 N R 9 E A-9
T _____ R _____
T _____ R _____
T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

Compliance with
ACT 345, P.A. 1990
APPROVED ON: 12-30-94
OAKLAND COUNTY REMONUMENTATION
PEER GROUP COMMITTEE
Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, THOMAS M. SMITH, in a field survey on DECEMBER 1, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													


NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

POST, G.L.O. 1817 P.K. SPIKE
L.C.R.C., L. 7455, PG. 853
1974

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

NO CORNER WAS FOUND. I REESTABLISHED THIS CORNER FROM THE WITNESSES IN LIBER 7455, PAGE 853



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9: I PLACED 5/8" ROD WITH BRASS CAP #31606 IN A NEW MONUMENT BOX.
N 45 E. 68.47' remon tag E. side P.P.
S 45 E. 65.00' to remon tag E. side P.P.
N 60 W. 76.20' to remon tag N.E. side P.P.
S 60 W. 70.80' to remon tag N. side P.P.

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE ORIGINAL CORNER.

Signed by [Signature]

Date DECEMBER 19, 1994

Surveyor's Michigan License No. 31606