LIBER 15292 pc 371

Mar 1595041983

NE T CANTEL

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE

OK - 1	T.	SM	ĺ	
--------	----	----	---	--

941%	Filing Requiren	nent of Act 74, Mich. P.A	- 1979 7.00 HISC RECORDING CHG - IN HOUSE
For corners in			\$ 2.00 REMON CHG - IN HOUSE
	OMMISSION In: WATERFOR	D Corner Code ##	15 MAR 95 8:08 A.M. RECEIPT# 8B
(County)			PAID RECORDED - OAKLAND COUNTY
1. Public Land Survey	T 3 N R 9 E	K=8	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
1. Public Land Survey	TR		
	TR		Compliance with ACT 345, P.A. 1990
	T R		12.20.64
2. Property Controlling	STR		APPROVED ON: 12 30 19 OAKLAND COUNTY REMONUMENTATION
in Section	S T R		PEFR GROUP COMMITTEE
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		negister of Deeds Stamp & Fire Number
4. Lot No	, Recorded Plat		A B C D E F G H I J K L
			2 - 6 5 4 3 2 1
			³ ├-┼-┼-┼-┼-┼-┼-┼
			4-7-4-8-4-10-4-11-4-13
. THOMAS M. SMITH	, in a field survey onNOVEMBE	R 24 199	<u>4. 5 </u>
do hereby certify that under	requirements of P.A. 74, Michigan P.A. of	1970, the corner points mention	ned 6 19 17 16 15 14 15
	e in conformance with regulations and		
Current manual of survey in:	structions of the United States Departm of a Court of Law and/or that the corner p	ent of the interior, Bureau of Li points mentioned in lines 3: 4 ar	
above were in conformance	with the rules of the Michigan Board of I	and Surveyors or by a Decree	ofa alililili
Court of Law; established	i, re-established, monumented, re-mo	numented, recovered, found	as
expressed below:			10 29 28 27 26 2
	I corners, all in the same town and	range, may be recorded	11 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-
on this certifica	te.		12 31 32 33 34 35 3
			13
A. Description of origin	al monument and accessories and/		~ / J
POST, G.L.O.	i" IRON IN MON. BOX	iron in mon bo	X.
1817	L.C.R.C.	L.C.R.C.	
	L. 7899 P. 731	L. 13427 P. 241	40
	WILLIAMS, 1980	VAN HAVERMAAT. 19	93
I FOUND A ½" LAKE ROADS. I LIBER 7899, F	ROD IN THE MONUMENT BOX AT VERIFIED THE CORNER WITH PAGE 731 & IN LIBER 13427, TO CLOSELY HIT PLATTED DIMI	AT THE INTERSECTION I THE L.C.R.C'S RECO , PAGE 241, ALSO ME	OF SCOTT LAKE & PONTLAC
K-8: I REPLACED N 45 W. 59.72' N 60 E. 57.19' S 45 E, 60.26'	THE ½" IRON WITH A 5/8" It or remon tag W. side P.P. to remon tag N.W. side P. to remon tag S.W. side P. to remon tag S.W. side P. to remon tag S.E. side P.	ROD WITH A BRASS CAN P. P.	
THE SELECTED LOC		AND IS GENERALLY AC	CEPTED BY PROFESSIONAL SERVEYORS

31606

Surveyor's Michigan License No.

FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1963

DateDECEMBER 19, 1994