

LIBER $21146 \sim 082$

MAY 2 4 2000

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE

59632

SECTION	Filing Requirement of Act 74, Mic	L.	BER	211	46 P	AGE	82					
For corners in		1 44	ን ለለ	OCMA!	ni fac n	RDING TATIO B:27_I	\ 1. M.	RF	CEIPT	# 16 !	518	
Oakland	Located In: Corner Code #	n/	STB	ĐC	COORE	D - 01 ELL,	ות או	10 13	IIIN T)5
(county)	Waterford Township											
1. Public Land Survey	T <u>3N</u> R <u>9E</u> <u>M-8</u>			Ca A⊮rm	887. ¹¹ .	:::e wh	น กกก					
	T R	PRO		F 1 1	11 -	~	770 4 E	.51	2			
C. Duran ata Cantasilina C	TR	PRO	YED ()N: O & IIs	YEV E	PMO:	er Managaran Maria (R. 2	energeneral TANT	A Traci			
in Section S	T R	. 5 4 5 4 7				4 'x 1848			/ N. S. & S.			
3. Miscellaneous S	Registe	er of	Dee	ds S	tamp	& F	ile	Num	ber			
 Property Controlling S	T R									,. <u></u> .		
							•					
4. Lot No, Recor	rded Plat		A	В	C D	E	F	3 f	1 1	J K	(L	
5. Private Claims			2							_ 	_	_
								Ĭ		<u> </u>	Li	ļ
1, Joseph C. Kapelczak, in a field s	survey on <u>April 9, 1999,</u> do hereby certify that unde 0, the corner points mentioned in lines 1 and 2	er requirements	1	Ţ	Π						\bigsqcup	2
conformance with regulations ar	nd rules therefore as required in the current ma	anual of survey	r l		ΙΪ					Ï	Li	Ĺ
instructions of the United States I	Department of the Interior, Bureau of Land Mana	agement or by a	- 1	Ţ							$\prod l$	9
decree of a Court of Law and/or the	nat the corner points mentioned in lines 3, 4 and 5 Michigan Board of Land Surveyors or by a Decr	s above were in ree of a Court of	,	-18— 	'		1	Ì			\Box	_
Law; established, re-established,	monumented, re-monumented, recovered, found	d as expressed		1]		
below:			9	-19	1		[آ				
		• 5	10	T								
A. Description of original mont	ument and accessories and/or subsequent re	estoration:	,,	-30— 	29		1			1		Ĺ
Set post in 1816 G.L.O. Survey.			12	-31-	32		33	3	4	-35		8-
There are no LCRC's recor			13	1_	11	_ _	1	Ш	L			_
	nce found and/or method applied in restoring	or reestablish	ina i	COFF	er:							
Court. A-8 of Pontiac Town	a monument in monument box located in the nship is 7.14' north of M-8 and on the Townsi Pontiac Hospital Survey of 1926.	e parking lot so hip Line. This	outh corr	of the	re Or vas v	aklan alida	d Co	oun with	ty Ci rec	rcuit ordec	d	
Recovered Witnesses:							9	,				
S 37°E 104.086' concrete r	nail south edge top of concrete light pole base nail in edge top of concrete light pole base. nail north edge top of concrete light pole bas							•				
	or corner and accessories established to per		ig th	e po	sitio	n of t	he c	om	er:			
Recovered brass disc in m										1	lp	
Set Witnesses:			-							1	2	
	n n de fer de Relaterale bere	-										
S 37°E 104.086' concrete r S 58°W 132.826' concrete	nail south edge top of concrete light pole base nail in edge top of concrete light pole base. nail north edge top of concrete light pole bas with tag southeast face 6" Crabapple. ontiac Township.		TANK TANK	, de 1	ROF	EPH ELCZ ESSICIVEYC	NAL		Particular Control			
•			The state of the s		PAOFE	4598 \$ 5 0\	W SI	N. S.				
					-441	2696949	1600					
									`			