_		40400 404	
		LIBER 18129 # 494	(1 년 사항
			· C
LAND CORNER RECORDATION CERTIFICATE			
Filing Requirement of Act 74, Mich. P.A. 1970			
	r corners in  Oakland Located In:	Corner Code #	\$ 7.00 PLECETTANEOUS RECORDING
	(County)		\$ 2.00 RENONUMENTATION O 23 FEB 98 11:13 A.M. RECEIPTR 156AL
1	Public Land Survey T 4N R	8E M-8	PAID RECORDED - DAKLAND COUNT►
1.	T R	` <del></del>	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
	<u>T P</u>		Compliance with ACT 345. P.A. 1990
2	T R Property Controlling S T R	BE MAIION	1-14-61-75
	in Section S T R		OAKLAND COUNTY REMOSUMENTATION
3.	Miscellaneous S T R	· · · · · · · · · · · · · · · · · · ·	PEER GROUP COMMUTTER Register of Deeds Stamp & File Number
	Property in Section S T R		
	Lot No, Recorded Plat	SECTION	A B C D E F G H I J K
5.	Private Claims		2 4 4 4 4
			3
		11 17 07	, 4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
1, <u>James J. Scharl</u> , in a field survey on <u>11-17</u> , 19 <u>97</u> , do hereby certify that under requirements of P.A. 74; Michigan P.A. of 1970, the corner points mentioned			
In lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current			
manual of survey instructions of the United States Department of the Interior, Bureau of Land  Management or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and			
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found			
	expressed below:	Official Red, 18-months med, 1900vered,	10 30 29 28 27 26 2
NO	TE: Not more than 4 corners, all in the same to	wn and range, may be recorded	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	on this certificate.		12 31 32 33 34 35 3
A.	Description of original monument and access		
	Post set in 1815 G.L.O. survey;	7" W. oak S 46°W 20 1ks;	8" B. Oak, N 28"E 34 1ks.
	LCRC, L 15686, P 189		
	Hart, 1995, set 1/2" rerod N 30°W 54.72° PK E 12° Pine		
	North 35.13 PK E 12" Pine		
	East 8.00' PK S 6" Elm	•	/
	South 12.09 PK W 8" Elm		v ark
		•	tablishing corner:
B.	Description of corner evidence found and/or method applied in restoring or reestablishing corner: $\int_{0}^{t}$		
	Recovered 1/2" rerod 323.11 ft south of West 1/4 corner of Section 19, '7' T4N, R9E. Corner was previously set by Hart in 1995 on line midpoint		
	between the NE and SE corners of	f Section 24, T4N, R8E, t	to establish the
	west line of "Bridge Valley II"	, recorded in L 245, P 38	8-41, O.C.R.
	Witnesses Found	•	Supplied to the second
	*N 30°W 54.72' PK E 12" Pine		SCHARL SCHARL
	*North 35.13' PK E 12" Pine *East 8.00' PK S 6" Elm		PROFESSIONAL A
	*South 12.09' PK W 8" Elm		SURVEYOR
	•		NO. 19843
	*Confirms LCRC from "Bridge Val	lev II"	THE COLAND SUR
_	_		
Ç,	Description of monument for corner and accessed concrete monument with O.C.		
			Plane Coordinates
	N 30°W 54.72' PK E 12" Pine North 35.13' PK E 12" Pine		
	East 8.00' PK S 6" Elm		649.9787 · 70269.9508
	South 12.09 PK W 8 Elm		·
	The selected location is accept	ed by the Contractor and	is generally accepted by profes-
	sional surveyors as the best av This corner was also accepted b	ailable evidence of the party bear	position of the original corner.
	Act 345 of P.A. 1990.	y the baktand bounty reel	. Of oah ap epeaptioned anner
		_	
C:-	900 V9 JCPa	, O	ACCEMBER 15 1997

Surveyor's Michigan License No.

19843

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983