LAND CORNER RECORDATION CERTIFICATE

		Filing Require	ement of Act 74,	Mich. P.A. 19	· _ 70 _{· ·}		:	
Fo	or corners in Oakland	Located In:	Corner Code	- #		CELLANEOUS RE	CORDING C	
	(County)	Eocated in.	Conter Code	³ "	\$ 2.00 REM 23 FEB 98 1	ONUMENTATION	RECEIPTH 156A	
				ŀ	PAID	RECORDED -	DAKLAND COUNTY C	
1.	Public Land Survey	T 4N R 8E					ISTER OF DEEDS	
		T R						
		T R		7. Bi	,	Compliance wit		
9	Property Controlling	T R ST R		TATION		1.14	-58 55	
۷.	in Section	S T R	1 Lancary		APPROVED O	DUNTY PL MOS	near minimipalizations	
3.	Miscellaneous	S T R	100 91 2	2000		GROVES		
	Property in Section	S T R	11.1 44.9		Register of D	eeds Stamp 8	File Number	
				La i				
		, Recorded Plat	SECTIO) <i>N</i>	A B	CDEF	<u> </u>	
J.	Private Claims	······································	· · · · · · · · · · · · · · · · · · ·					
					3			
					4		10-1-11-1-1:	
Ι,	James J. Scharl	L, in a field survey on	11-18	, 19 <u>97</u> ,	5			
do	do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned							
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land								
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 8 19 20 21 22 23 2.								
		ce with the rules of the Michigan Bo			9			
	cree of a Court of Law; e: expressed below:	stablished, re-established, monumen	itea, re-monumentea, i	recovered, found	1030-	2928	27 26 2!	
	•	corners, all in the same town and	l range, may be race	orded	11	1-1-1-1		
	on this certificate				12 -31-	32 33	34 35 36	
	Danadakan at adalah				13			
A.	-	al monument and accessories a	•		1 77 0-1-0	70011 66 6	11	
		15 G.L.O. survey; 14" V		/1 1Ks; 14		79°W 66 1		
	LCRC, L 6868, P 370 LCRC, L 7466, P 148 LCRC, L 17188, P 329 Heil, 1977, 1/2" iron rod Williams, 1979, 3/8" rerod Ward, 1997, 5/8" rerod NW 1" pipe 39.48' West 15.03' nail N 6" Cherry *N 05°E 64.84' N/disc 12" F East Pipeline sign 29.20' N 85°E 61.72' nail N 30" Oak *N 70°E 61.32' N/disc 22" C							
	South 1/2" iron	29.70° nail NE	36" 0ak			Lsc 10" Map1		
	West Nail 8" s	stump 15.00'					isc 28" Oak	
					A	11 disc	- Core	
The state of the s							OF MICHIE	
8.	Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered 5/8" rerod, reset in February of 1997, approximately 5 ft SCHARL						IAMES J	
							SCHARL &	
	south of the so	south edge of Foster Road. Corner falls on the extension PROFESSIONAL						
	of a north-south tree row. Corner was reestablished from local surveys SURVEYOR							
	litnesses Found NO. 19943							
	*N 05°E 64.84'	PK/disc E 12" Hickory	*N 10°W 29.				SUR SUR	
		PK/disc N 10" Maple PK/disc SE 36" Oak		75' PK E fa 90' PK N fa			NO CONTRACTOR OF THE PARTY OF T	
	"H 10 W 27.J1	INJUISC DE 30 VAN		40' PK S fa			1 .	
			2	10 111 0 110		J.LE		
	*Verifys LCRC.	,					7,00 FILE	
	"Verliye boxo.						1"	
					•		7 "	
C.	Description of monu	ment for comer and accessories	s established to per	petuate locating	the position	of the corner:		
		onument w/O.C. remonume						
	N 70°W 74.40' PK/remon tag S face 36" Maple			State Plane				
	N 10°W 29.31' H	† Ools						
		K/remon tag W face 12'		N 447311.56 E 13370474.				
	East 65.92' PK/remon tag S face 18" Oak			E 133/04/4.	.0431			
		K/remon tag E face 4"						
	S 45°W 21.93' PK/remon tag N face 10" Maple							
	The selected location is a careful and faithful reestablishment of the position							
of the original corner. This corner was also accepted by the Oakland County Peer Group, as established under Act 345 of P.A. 1990.								
	reer Group, as	established under Act	545 OI. P.A. 1	990.				
Sia	ned by	mo Ochar		Date	DECEM	BER 15	1997	
-)	ELEMENTO PAR SO SON	
our	veyor's Michigan Lice	13043		FORM APPROVED B	THE PARTICION OF THE PORT OF T	ARD OF PROFESSIONAL	BURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983	