## SURVEY & REMONUMENTATION


under Act 345 of P.A. 1990.

Surveyor's Michigan License No.

19843

Committee of the second second second

## LIBER 15235 FG 075



LAND CORNER RECORDATION CERTIFICATE MAY - 1 1995 OK - T. SMITH Filing Requirement of Act 74, Mich. P.A. 1970 For corners in COMMISSION \$ 7.00 MISCELLANEOUS RECORDING \$ 2.00 REMONUMENTATION Oakland Corner Code ## Located In: County RECEIPT# 50B 2 FEB 95 9:41 A.M. RECORDED - OAKLAND COUNTY T 4N R 9E G - 10PAID 1. Public Land Survey LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
Compliance with T \_\_\_\_ R \_\_ \_\_ R\_ ACT 345, P.A. 1990 R 1-25-95 APPROVED ON: \_ T \_ \_\_ R \_ 2. Property Controlling OAKLAND COUNTY REMONUMENTATION \_\_\_\_ T \_\_\_\_ R \_\_ in Section PEER GROUP COMMITTEE R \_ T \_ Miscellaneous Register of Deeds Stamp & File Number Property in Sec. \_ , Recorded Plat \_\_\_ 5. Private Claims \_ December 20 I James J. Scharl , in a field survey on . \_ , 19 \_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: Post set in 1817 G.L.O. survey; N 68°E 40 1ks, 7" B. Oak; N 86°W 28 1ks, B. Oak LCRC, L12310, P025 Wozniak, 1992 Set capped iron #15066 N 15°E 7.23' SW face fence post 28.32' PK N side util pole \*East 7.70' PK W side trip 8" tree S 15°W B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered 1/2" rerod on north-south tree line with old fence line remnants to the north. A tree line also runs west from the corner. annanana ka OF MICHIGAN Witness Found 28.58' PK S face DE pole East 28.32' PK N face DE pole \*East 42.04' PK W face twin 16" Cherry South **PROFESSIONA** SURVEYOR LAND \* Confirms LCRC witness C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set concrete monument with Oakland County Remonumentation brass cap, replacing the 1/2" rerod. 16.61' PK/Remon tag 12" Box Elder N 45°E 28.60' PK/Remon tag S face DE pole East 42.03' PK/Remon tag W face 16" Cherry South 35.68' PK/Remon tag S face 30" Cherry West S 60°E 43.63' NW cor block bldg The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also acceptd by the Oakland County Peer Group as established

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Q

Date <u>Dec. 28, 1994</u>