## SURVEY & REMONUMENTATION

10

11

7.00 MISCELLANEOUS RECORDING

MAY - 1 1995

For corners in

Property in Sec.

LAND CORNER RECORDATION CERTIFICATI

2.00 REHONINENTATION

· ····································	FAAA MENANTHING SAN			
LAND CORNER RECORDATION CERTIFICATE	FEB S	75 9142 A.H.	RECEIPT# 50B	
Filing Requirement of Act 74, Mich. P.A. 1970PA	ID	RECORDED -	OAKLAND COUNTY	

_ C	Oakland COMN	ISSION Located In:	Corner Code ##
	(County)		
1.	Public Land Survey	т <u>4N</u> в <u>9Е</u>	G-12
		T Ř	<del></del>
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	

LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

## OK - T. SMITH

Compliance with ACT 345, P.A. 1990

/-25-95 APPROVED ON-OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deeds Stamp & File Number

I.	Lot No,	Recorded Plat	 	 
,	Private Claims			

December 20 James J. Scharl , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Post set in 1817 G.L.O. survey

LCRC, L12290, P167

Smith, 1992

S 33°E 12 1ks 14" W. Oak

1" steel bar in mon box

N 24°E 66 1ks 20" W. Oak \*North

73.46', PK/flasher E side 4" Elm N 15°W

50.47', PK W side P.P. 58.20', PK W side 16" Oak \*N 15°E 39.83', PK E side P.P. \*South

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered 1" iron bar in monument box, positioned 1.5 ft north of the centerline of Pelton Road. A tree line runs north and a fence line runs south from the corner.

Witnesses Found nail E face 26" Walnut N 20°E 29.02' 44.97' nail W face 16" Walnut N 15°E 58.22' N/tag W face 18" Walnut \*N 10°E 50.53' PK/tag W face DE pole \*North 39.86' PK E face DE pole \*South



## \*Confirms LCRC witness

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" rerod with Oakland County remonumentation brass cap in monument box, replacing l" iron bar.

28.97' PK/remon tag E face 26" Walnut N 20°E

50.52' PK/remon tag W face DE pole North

39.89' PK/remon tag E face DE pole South

78.00' PK/remon tag E face steel fence post (Main post) S 45°E

LONG TO A CONTROL OF THE STREET OF THE STREE

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also acceptd by the Oakland County Peer Group as established under Act 345 of P.A. 1990.

Signed by . Surveyor's Michigan I license N

\_\_\_ Date \_\_\_\_ <u>Dec. 28, 1994</u>

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197! REVISED JAN., 198: