
## SURVEY & REMONUMENTATION

## 118th 15235 ki 095



MAY - 1 1995

Surveyor's Michigan Licen

LAND CORNER RECORDATION CERTIFICATES 7.00 HISCELLANEOUS RECORDING Filing Requirement of Act 74, Mich. P.A. 1970\$ 2.00 REHONNENTATION

For corners in COMM	NSSION Filing Requ	irement of Act 74, Mich. P.A. 1	
Oakland (County)	Located In:	Corner Code ≠	2 FEB 95 9:44 A.N. RECEIPT# 50B PAID RECORDED - GAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
Public Land Survey	T <u>4N</u> R <u>9E</u> T R		OK - T. SMITH  Compliance with ACT 345, P.A. 1990
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R S T R S T R S T R		APPROVED ON: 1-25-95 OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deeds Stamp & File Number
4. Lot No, I	Recorded Plat		
			A B C D E F G H I J K L
			3 4 7 8 8 10 10 11
do hereby certify that under re- in lines 1 and 2 above were in current manual of survey instr Management or by a decree of above were in conformance wi	n conformance with regulations a ructions of the United States Dep a Court of Law and/or that the cor ith the rules of the Michigan Board	December 16, 19 94  A. of 1970, the corner points mentioned and rules therefore as required in the artment of the Interior, Bureau of Landiner points mentioned in lines 3, 4 and 5 d of Land Surveyors or by a Decree of a se-monumented, recovered, found as	5 6 -18 -17 -16 -15 -14 -1 7
NOTE: Not more than 4 con this certificate.	corners, all in the same town	and range, may be recorded	11 12 31 32 33 34 35 3
A. Description of original	monument and accessories a	and/or subsequent restoration:	13
Post set in 1817 G.L.O. survey S 68°W 30 1ks 6" N 79°E 74 1ks 6"	Scharl, 1		100
	B Oak N 10°E 1 *East S 20°E 2	15.18' nail SE side 24" 19.42' nail S side 30" O 20.60' nail SW side 36" 19.36' nail N side 6" Oa	ak Oak
	pe at the intersection	d applied in restoring or reestablison of a north-south and	ching corner: east-west fence/tree line.
*N 85°E 19.45' PK S 15°E 20.16' PK			JAMES J. SCHARL PROFESSIONAL SURVEYOR NO. 19843
*Confirms LCRC wi			
		s established to perpetuate location	
Set concrete monu	ment with Oakland Co	inty remonumentation bra	ss cap, replacing 1/2" pipe.
N 85°E 19.47' PK S 15°E 20.08' PK	/remon tag E face 14' /remon tag S face 18' /remon W face 26" Oak /remon tag N face 7"	'Oak	
professional surv	eyors as the best ava		nerally accepted by position of the original eer Group as established
	on Schou	Q _ Date	Dec. 28, 1994

SEASTINETY, SERVICE THE

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1983