LIBER 15305 rc 860

MAY 1 & 1006

4. Lot No. .. 5. Private Claims _

expressed below:

MAL T O 1000	LAND COR	NER RECORDATION CERTIF	ICATE		
or corners i COMMISSION	Filing Requ	HISCELLANEOUS RECORDING			
_				REHONUMENTATION	
Oakland	Located In:	Corner Code =##	23 MAR	95 9:51 A.M.	RECEI

T 4N R 9E M-2**Public Land Survey** T _____ R __ R. T 2. Property Controlling . R. in Section Miscellaneous S _ T .____ R . Property in Sec. S _ T _ _ R .

__ , Recorded Plat __

PT# 14B RECORDED - DAKLAND COUNTY PATH LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

> Compliance with ACT 345, P.A. 1990

2-15-95 APPROVED ON: OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deeds Stamp & File Number

James J. Scharl , in a field survey on	December 14					
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						
in lines 1 and 2 above were in conformance with regul						
current manual of survey instructions of the United Stat						
Management or by a decree of a Court of Law and/or that						
above were in conformance with the rules of the Michiga						

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

11

 A. Description of original monume 	ent and accessones and/or subse	equent restoration:	
Post set in 1817 G.L.O.	survey; S 35°W 17 lks,	14" W Oak; N 46°E 30 1ks,	20" W Oak.
Baldwin	O.C.R.C.	LCRC, L7288, P542	LCRC, L12313, P878
Iron pipe	1952	Kennedy, 1978	Ward, 1992
NE 39.15' 6" Oak	Found 3/4" IP	Found 1/2" iron rod	Found iron rod
NE 41.55' 14" Twin Oak	North 40.78' 18" Elm .	N80°W 38.85' 16" Walnut	
*SW 40.2' Gate post	SE 58.40' Stone	South 56.11' 5" Elm	*N85°E 83.97' N/disc
SE 58.3' Gate post	gate post	*S20°W 39.60' P. Pole	L. pole
	*SW 40.45 Stone		*S15°E 97.32' N/disc
	gate post		Maple cluster
	•	•	*S30°W 39.46' N/disc

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered 1/2" rerod on centerline of Indianwood Road on S'ly extension of centerline Baldwin Road.

Witnesses Found *N 65°W 51.31' PK/tag S face 20" Oak 59.51' PK/rag S face DE pole N 45°W 83.97' PK/tag S face light pole 97.48' PK/tag E face Maple cluster *N 85°E *S 15°E 39.50' PK/tag S face DE pole *S 40°W 40.44' NW corner, stone gate post



*Confirms LCRC witness

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" rerod with 0.C. remonumentation brass cap in monument box, replacing 1/2" rerod.

N 45°W 59.53' PK/remon tag S face DE pole 51.30' PK/remon tag S face 20" Oak N 65°W 39.30' PK/remon tag S face DE pole S 40°W 84.12 PK/remon tag S face light pole S 45°W 40.44' NW corner stone gate post

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990.

____ Date ___ February 10, 1995 Signed by 19843 Surveyor's Michigan L FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28, 1971

USED MAY 14, 1975 REVISED JAN., 1983

P. pole