

Mar 2395047323

MAY 1 6 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COPY	3
------	---

For <u>scor</u> ners in			•	\$ 7.00 HISCELLANEOUS RE	\$ 7.00 HISCELLANEOUS RECORDING		
Oakland Co	eunty)	Located In:	Corner Code ##	\$ 2.00 REMONUMENTATION 23 MAR 95 9:52 A.N.	RECEIPT# 14B		
1. Public Lan	d Survey	T <u>4N</u> R <u>9E</u> T R	M-13	PAID RECORDED - LYNN D. ALLEN, CLERK/REG	OAKLAND COUNTY ISTER OF DEEDS		
		T R		Compliance with ACT 345, P.A. 199			
2. Property C in Section	s	T R T R	4.	APPROVED ON: 2-/5- OAKLAND COUNTY REMONU PEER GROUP COMMI	MENTATION		
3. Miscellane Property in		T R		Register of Deeds Stamp &	File Number		
		ed Plat		A 8 C D E F G	H J K L h		
do hereby certify	y that under requiremen	nts of P.A. 74, Michigan P.A	ember 15 , 19 94 of 1970, the corner points mer	ntioned 6	-101112		
current manual of Management or la above were in co	of survey instructions of by a decree of a Court of onformance with the rulestablished, relestab	of the United States Depar of Law and/or that the corne les of the Michigan Board	nd rules therefore as required rtment of the Interior, Bureau of er points mentioned in lines 3, of Land Surveyors or by a Deci monumented, recovered, for	I in the of Land 7 4 and 5 8 19 20 21 ree of a	-22 -23 -24 -27 -26 -25		
	ore than 4 corners, s certificate.	all in the same town a	nd range, may be recorde	d 11 12 31 32 33	-343536		
•	•		d/or subsequent restoration				
	in 1817 G.L.O M.S.H.D. 195		49 1ks, 13" W Oak; RC, L11945, P516	S 20°E 100 1ks, 12" W Oa	k. 30		

Dedecker, 1991

*S 74°E 24.92' Nail/MSHD washer S face 42" Oak

*S 71°W 67.22' PK N face 10" Hickory
N 54°W 42.27' PK S face 10" tree
N 20°W 54.36' Nail/tag W face utility pole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered 1/2" rerod at the centerline intersection of the E'ly extension of Mann Road from west and the N'ly extension of Rohr Road from the south. A tree/rock row runs east from the corner.

Witnesses Found

1/2" rerod found

N 55°W 42.37' 5" Beech

S 55°W 42.14' 8" Beech *S 85°E 24.85' 31" Oak

*S 74°E 24.94' PK/tag S face 44" Oak *S 70°W 67.16' PK N face 12" Hickory

N 55°W 23.32' PK S face light pole



REVISED MAY 14, 1975

*Confirms LCRC witness

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 5/8" rerod with 0.C. remonumentation brass cap #31606 when final witnesses were located.

East 22.90' PK/remon tag #31606 N face 36" Oak

N 45°W 42.32' PK/remon tag #31606 S face 12" Hickory

S 45°E 76.10' PK/remon tag W face 16" W Pine

S 74°E 24.94' Nail/MSHD washer S face 42" Oak

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990.

	0.0.2.	Date	February 14, 1995
Signed by	7,0 cm	Date	Tobludly 14, 1999
Surveyor's Michigan Lidense No.	19843		THE STATE OF THE S

中國的語句是