1182 152 25 rc 656

Jan 2795016442

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE 7_00 HISCELLANEOUS RECORDING

For corners in Oakland		Located In:		Orion	Requirement of Act 74, Mich. Orion Twp. Corner Code ##			27 JAN 95 11:01 A.M. RECEIPT# 76B PAID RECORDED - OAKLAND COUNTY									
1. F	Public Land Survey		T 4N R 10E H-13 T R					A second and a second a second and a second									
. i 3. N	Property Controlling In Section Miscellaneous Property in Sec.	s s	T T T T	_ R _ R _ R _ R					ı	ED O ID CO EER	N: DUNI GRO	345, I <i> 2-</i> - Y R OUP	P.A. 29_ EMO COM	1990 24 NUM MITI	ENT FEE	`ATIO	-
	ot No, R								<u>^</u>	в с	: D	Ĕ.	F G	H 	<u>L</u>	K L	<u>L</u>
ı Hu	ston K. Kennedy	in a fie	eld survev	on	Dec	ember 20	19 94	-	3 4) 	- 8-		9		-	1	-12-
do he in line curre Mana	reby certify that under req es 1 and 2 above were in nt manual of survey instru gement or by a decree of a	uirement conform ctions of Court of	s of P.A. 74 nance with the United Law and/o	, Mich regul d Stat r that	nigan P.A. of ations and es Departm the corner p	f1970, the corner p rules therefore as lent of the Interior, points mentioned in	oints mentioned required in the Bureau of Land n lines 3, 4 and 5		6	8	-17- -20-	1	6	15	1	4	-13
	e were in conformance wit of Law; established, re			_		•	,		9	-	-	-	$\vdash \downarrow$		\perp		+

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

1817-GLO Wampler, D.S.; No Post - In Lake - No Witnesses

expressed below:

on this certificate.

- 1.) 1978-Lippincott, P.S. #25855; LCRC L.7372, Pg.854 Fnd 5/8" Re-rod in Monument Box
- 2.) 1980-0'Rourke, P.S. #16937; LCRC L.7771, Pg.608 Fnd 1" Iron Bar in Monument Box 3.) 1990-Wozniak, P.S. #15066; LCRC L.11580, Pg.542 Fnd Iron w/cap #16937

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1994 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 1/2" Iron Rod in a Monument Box in the centerline of the East bound lanes of Brown Road, which has a concrete surface. Found second 1/2" Iron Rod in a Monument Box 59.47' due West in the centerline of Giddings Road to the South, which is the North 1/4 corner of Section 3, T3N, R10E, (H-1).

Witnesses from LCRC #3 were used to recover and verify the location of the found 1/2" Iron Rod in a Monument Box.

I accept the found 1/2" Iron Rod in a Monument Box as the best evidence of the original corner position.

FIELD MEASUREMENT BETWEEN

H-13 to G-13 2681.66 Ft. (L.7766, Pg.179)

H-13 to I-13 2724.09 Ft. (L.7766, Pg.179) H-13 to H-3 59.47 Ft. (Pontiac Twp.) H-13 to H-3

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - H-13 I replaced the found 1/2" Iron Rod with a 5/x8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland County Remonumentation, PS #17623 N52 W 124.45' Set PK & Remon. Washer South face Power Pole

N65°E 178.20' Set PK & Remon. Washer SE face Power Pole

S78 W 115.17' Set PK & Remon. Washer South face Power Pole

S05'W 37.09' Set PK & Remon. Washer East face Power Pole

The selected location is accepted by me and is generally accepted by Professional Surveyors as of the position of the original corner. ROFESSIONAL

Signed by Surveyor's Michigan License No.

Date January 18,

> APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197

PROFESSIONA

willian .

REVISED JAN., 1983