## SURVEY & REMONUMENTATION

Surveyor's Michigan License No.

## USER 15225 PC 657

Jan 2795016443

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28,

REVISED JAN., 1983

MAY - 1 1995 LAND CORNER RECORDATION CERTIFICATE 7.00 MISCELLANEOUS RECORDING COMMISSION Filing Requirement of Act 74, Mich. P.A. 1978 2.00 REMONUMENTATION For corners in 27 JAN 95 11:01 A.M. RECEIPT# 76B Located In: Orion Oakland Corner Code ## RECORDED - DAKLAND COUNTY PAID Twp. LYNN D. ALLEN, CLERK/REGISTER OF DEEDS T 4N R 10E I-8 **Public Land Survey** OK T. SMITH \_\_ R \_\_\_\_ \_ R ACT 345, P.A. 1990 T \_\_ R \_\_ 12-29-94 APPROVED ON: **Property Controlling** \_ R \_ OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE \_ R \_ \_\_ T \_ in Section \_\_\_ T \_\_ \_\_ R \_\_ Miscellaneous S Register of Deeds Stamp & File Number R Property in Sec. Т \_ , Recorded Plat \_ 5 Private Claims Huston K. Kennedy , in a field survey on December 20 <sub>. 19</sub>94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: 1817-GLO Wampler, D.S.; Set Post; 10" White Oak S58\*E 7 Links; 4" Black Oak N79\*W 40 Links There are no recorded LCRC's or recorded or unrecorded Certificates of Survey for this corner B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1994 Kennedy Surveying, Inc. - Kennedy, P.S. #17623 - Fnd 1/2" Iron Rod 2" above ground with a fence line extending South, East, West and 29 feet North to a plowed field. The description to the East was used to verify the location of the found 1/2" Iron Rod FIRED HRASURENESS BETWEEN I-8 to J-8 1985.91 Ft. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner; I-8 I replaced the found 1/2" Iron Rod with 1/2" Iron Rod encased in a 4" diameter concrete cylinder 36" long w/2" diameter brass cap stamped Oakland County Remonumentation, PS #17623. Due South 2.40' Set PK & Remon. Washer West face 27" Hickory S13'W 26.72' Set PK & Remon. Washer West face 11" Elm MICHIG S88°W 16.70' Set PK & Remon. Washer South face 36" Oak S88'K 12.89' Set PK & Remon. Washer North face 8" Klm The selected location is accepted by me and is generally accepted by Professional Surveyors as the bes lab KENNIGOYCE position of the original corner. January 12, 1995 \_\_ Date .